1939

MCR North Jetty

2002

Loss of ebb-tidal shoal evident at the North Jetty.

MCR Jetty Repair – Figure 3