


APPPENDIX A ENVIRONMENTAL APPENDIX


CONTENTS


- 1. Figures and Photos
- 2. Historic Resources
- 3. Environmental Justice
- 4. Waterk UmAssessment Model
































Cedar Creek Planning Area: Existing Conditions Photos



Cedar Creek Headwaters



Cedar Creek intake structure (March 2006)




Cedar Creek main stem



Cedar Creek water control structure near intake



North Branch and South Branch of Cedar Creek with the McKenzie River is distance (looking north)



1996 Flood (McKenzie River/Cedar Creek floodplain) - Looking West



South Cedar Creek




1996 Flood (McKenzie River/Cedar Creek floodplain) - Looking South



North Cedar Creek



1996 Flood (McKenzie River/Cedar Creek floodplain) - Looking West



Blue Water Ponds and Keizer Slough



69th Street Channel



72nd Street Channel



Gray Creek at Bob Artz Park



Historical Resources in Amazon and Cedar Creek Planning Areas

Amazon Creek Historical Resources and Parks and Open Space Map

The map shows all parcels within the city of Eugene that are listed on the National Register of Historic Places, or that are designated city landmarks. The two historic districts listed on the National Register are indicated. Those parcels on the map and listed below that are neither on the National Register nor a designated city landmark are in the City of Eugene's database of significant historical resources. Locations of the Lane County significant historic resources within the Amazon Creek Planning Area that are listed in the *Working Paper: Historical Resources Lane County Comprehensive Plan Revision* also are included on the map. City landmarks and city and county historical resources have the potential for being listed on the National Register.

The Area of Potential Effect is a ¼ mile radius from the main waterway and is used in determining possible environmental effects of project actions.

Amazon Creek Existing Historical Resources

Table A-6.1 City of Eugene Historic Sites within Amazon Creek Planning Area

ADDRESS	NAME	NATIONAL REGISTER	CITY LANDMARK
814 Lorane Highway	Young-Pallett House Kjaer House		х
595 Crest Drive	Wayne Morse Farm	х	
26th and University	Hope Abbey Mausoleum	х	х
26th and University	Masonic Cemetery	х	х
2237 Spring Boulevard	Hampton/Church House		
447 W 22nd Ave	Kerns/Chase House		х
930 East 21st Avenue	James S. McMurray House		
2058 Olive Street	Archie Tirrell House		
2056 Lincoln Street	Frederick Smith House		
96 W 20th Avenue	Edgar Moore House		х
2050 Madison	Masterson House		х
2000x Fairmount Blvd	Hendricks Park		
1900 Olive Street	Columbia College Marker		
1740 Lawrence Street	Elliott-Barker House		
University of Oregon	Music Building		
60 West 17th Avenue	Elkins Residence		
1718 Lincoln Street	Marx-Schaefers Residence		
707 East 17th Avenue	Benjamin Franklin Dorris House	х	
1694 Washington Street	Wright House		
1659-1691 Olive Street	Peterson Row Houses		
485 West 17th Avenue	Weinstein Residence		
1654 Lincoln Street	Mickelson Residence		
1661 Washington Street	Himber Residence		
1660 Washington Street	Krey House		
244 East 16th Avenue	Christian/Patterson Rental	х	х
1605 Pearl Street	Patterson/Stratton Residence x		
1626 Willamette Street	Veterans Memorial Building		
1601 Olive Street	Lane Tower		


1610 Olive Street	Hamaker Residence		
1611 Lincoln Street	A.V. Peters-Liston-Wintermeire House	Х	х
1596 Olive Street	Barnes Rentals		
1585 Lincoln Street	White Residence		
University of Oregon	Education Building 1916		
18th and University -			
NWcorner	Eugene Pioneer Cemetery	Х	X
1542 Washington Street	Robinson Residence		
1464 Lincoln St	Coombs-Davis House		
1475 Washington Street	Luckey-Gardner Residence		
1466 Washington Street	Lyons Residence		
1421 Lawrence Street	Erdman House		
1418 Olive Street	Parsons Residence		
1396 Charnelton Street	Bion Drake Rental		
1338 Charnelton Street	Cook Residence		
740 West 13th Avenue	Lane County Clerk's Building	Х	х
1331 Washington Street	Larson Residence		
1312/1330/1338 Lincoln			
Street	Ball House Ensemble		X
590 West 13th Avenue	Skinner Residence		X
1308 Jefferson Street	G.W. Hunter Residence		
1280 Willamette Street	Kennell Ellis Building		X
227 West 15th Avenue	Ralph Newman Residence		
1272 Willamette Street	Florence Apartments		
601 West 13th Avenue	McNail-Riley House		
1240 Monroe Street	Johnson House		
650 West 12th Avenue	Lincoln School	Х	
990 West 12th Avenue	Arthur A./Ella Maring House		
835 West 12th Avenue	Holcomb House		
1390 West 10th Avenue	Ranch House		
1006 Taylor Street	Chambers House	Х	Х

Table A-6.2 Lane County Comprehensive Plan Historical Resources within Amazon Creek Planning Area

Type of Site	Site #	Township-Section-Range	Site Name
Cemeteries	C-26	16-05-24	Caldwell
	C-44	18-04-05	Gates of Heaven
	C-83	17-04-33	Bethesda
Farms	F-16	17-04-05	Ray & Margorie Bond
Grange Halls	G-3	18-04-03	Four Oaks

METROWATERWAYS

Historical Resources--Amazon Creek Planning Area



Cedar Creek Historical Resources and Parks and Open Space Map

The map shows the properties within the city of Springfield that are listed on the National Register of Historic Places, and includes two historic districts, Washburne Historic District and Dorris Ranch. The list below includes properties on the National Register and those listed by the City of Springfield as City Landmarks.

Locations of the Lane County significant historic resources near the Cedar Creek Planning Area that are listed in the *Working Paper: Historical Resources Lane County Comprehensive Plan Revision* also are included on the map, with the exception of two properties that are more than 1 mile from the planning area boundary and are not within the map extent. The Thurston Grange Hall is the only historic property within ¼ mile radius of proposed project sites. It is a city landmark but not listed on the National Register. City landmarks and city and county historical resources have the potential for being listed on the National Register.

The Area of Potential Effect is a ¼ mile radius from the main waterway and is used in determining possible environmental effects of project actions.

Cedar Creek Historical Resources

Table A-6.3 Historical Resources within the Cedar Creek Planning Area

ADDRESS	NAME	NATIONAL REGISTER	CITY LANDMARK
6590 Thurston Road	Thurston Grange Hall		х

Table A-6.4 Historical Resources in the Springfield Area near the Cedar Creek Planning Area


ADDRESS	NAME	NATIONAL REGISTER	CITY LANDMARK
1260 Main Street	Brattain-Hadley House	х	X
590 Main Street	Pacific Power and Light Building	х	X
330 Main Street	Stevens & Perkins Building		х
342-246 Main Street	I.O.O.F. Building		х
890 Aspen Drive	Campbell House	х	
101 South A Street	Southern Pacific Railroad Depot	Х	Х
532 C Street	Ebbert Memorial United Methodist		Х
606 D Street	McKlin House		Х
846 F Street	Springfield General Hospital	x	Х
S 2nd and Dorris Ave	Dorris Ranch	Х	
214 Pioneer Parkway West	Stewart House		Х
3362 Osage	Douglas House		Х
33 city blocks	Washburne District	х	


Table A-6.5 Lane County Comprehensive Plan Historical Resources Within or Near Cedar Creek Plan Area

Type of Site	Site #	Township-Section-Range	Site Name
Cemetery	C-33	17-03-35	Springfield Memorial
Farm	F-31	17-25-35	Herbert Gray Century Farm
Grange Hall	G-23	17-02-34	Thurston Grange Hall



Historical Resources, Parks & Open Space -- Cedar Creek Planning Area





Environmental Justice/Title VI Populations Amazon Creek and Cedar Creek Planning Areas

Metro Waterways Study Area Map - Depicts Population Density within the larger study area


Population data in all maps are from the 2000 US Census.


The Area of Potential Effect in both Amazon and Cedar Creek Planning Areas is a ¼ mile radius from the main waterway and is used in determining possible environmental effects of project actions.


Amazon Creek Planning Area Maps


- **5-1 Neighborhood Associations**. This map depicts the existing neighborhoods defined by the City of Eugene, along the Amazon Creek corridor.
- **5-2 Population Density**. This map shows population density by number of persons per square mile in the planning area, using the census blocks that are wholly or partially within the study area boundary.
- 5-3 Population Density for Age 65+ (Senior Population). This map shows population
 density of people aged 65 or older by number of persons per square mile in the planning
 area, using the census blocks that are wholly or partially within the study area boundary.
- **5-4 Percent Minority**. This map shows percent minority in the population by block group using the census blocks that are wholly or partially within the planning area boundary.
- **5-5 Percent Disabled**. This map shows percent disabled in the population by block group using the census blocks that are wholly or partially within the planning area boundary.
- 5-6 Percent Households in Poverty. This map shows percent households in poverty in the population by block group using the census blocks that are wholly or partially within the planning area boundary and using the federal guidelines for definition of poverty level.


- **5-7 Population Density**. This map shows population density by number of persons per square mile in the study area, using the census blocks that are wholly or partially within the planning area boundary.
- 5-8 Population Density for Age 65+ (Senior Population). This map shows population density of people aged 65 or older by number of persons per square mile in the study area, using the census blocks that are wholly or partially within the planning area boundary.
- **5-9 Percent Minority**. This map shows percent minority in the population by block group using the census blocks that are wholly or partially within the planning area boundary.
- **5-10 Percent Disabled**. This map shows percent disabled in the population by block group using the census blocks that are wholly or partially within the planning area boundary.
- **5-11 Percent Households in Poverty**. This map shows percent households in poverty in the population by block group using the census blocks that are wholly or partially within the planning area boundary and using the federal quidelines for definition of poverty level.














Technical Appendix A

Waterway Assessments

Cedar Creek Priority Planning Area



















Prepared by the City of Springfield and Lane Council of Governments

Draft, April 2007



Table of Contents

Introduction	Page 1
Description of the Cedar Creek Planning Area	Page 1
Channel Assessment Scoring Summary Table	Page 3
Maps	Page 5 - 8
Waterway Scoring Worksheets	Page 9 - 135

Introduction

The thirteen waterway assessments included in this report represent qualitative and quantitative evaluation of all major waterways within the Cedar Creek Priority Planning Area. The extents of the reaches were determined so that they closely matched the location of proposed enhancement alternatives being looked at under the Metro Waterways Study.

The assessments are based on a combination of on-the-ground data collected by the City of Springfield in summer 2006, supplemental field data collected for some waterway segments by Lane Council of Governments in March 2006, and other off-site analysis. The assessment methodology is an adaptation of several existing standard federal and state methodologies that were customized for local conditions and the needs of the Metro Waterways study. Each waterway assessment was evaluated under four categories, which included physical conditions; water quality treatment potential; natural resource values; and recreation values. Within each of these categories, specific aspects of channel health were rated on a scale of 1 to 10, with 1 being poor and 10 being excellent. These individual scores were compiled into an overall rating of stream health. Reaches could receive up to 160 points. The final scores, presented as total points as well as percentages, are an indication of the overall health and functionality of that reach. These scores allow comparison with other waterways in the Metro Waterways Study Area (such as Amazon Creek) as well as pre- and post-enhancement comparison.

Description of the Cedar Creek Planning Area

Cedar Creek is a tributary of the lower McKenzie River, which drains a watershed approximately eleven square miles in size. Cedar Creek and its tributaries can be divided in to three distinctive types of waterway based on physical characteristics.


The first consists of the main channel of Cedar Creek which flows through the flat bottomland parallel to the McKenzie River. This channel originates in the Cedar Flat area, where if flows through the floodplain of the Thurston area (East Springfield) before branching into the North and South Cedar Creeks. These two forks rejoin again briefly around the Willamalane Lively Swim Park, before entering the McKenzie River through several braided channels. This main channel covers approximately eight miles.

The second distinctive waterway type includes the headwaters of Cedar Creek, which are a collection of unnamed feeder creeks which flow out of the Thurston Hills to the south of the main channel. Cougar Creek and Gray Creek are the only named tributaries in this area, but a number of additional small tributaries are located here.

The third waterway type includes an assemblage of channels associated with the City of Springfield storm water system, most of which drain into South Cedar. There are a total of six minor outfalls and four major outfalls from the City's stormwater drainage system that flow directly into South Cedar Creek. The major outfalls are the 72nd Street Channel, the 69th Street Channel, the Levi Landing Subdivision outfall, and the 64th Street Outfall. Each of these major outfalls are significant drainage basins.

Cedar Creek Priority Planning Area: Channel Assessment Scoring Summary Table

			Physical Assessment			Water Quality Assessment			Natural Resources Assessment				Recreation Assessment											
Waterway	Reach	Physical	Bank Stability	Bed Stability	Sediment	Physical Total	Absorption/Filtration	Aeration	Temperature	Bank Integrity & Protection	Water Quality Subtotal	Riparian Width	Habitat Diversity	Invasive Plant	Aquatic habitat	Wildlife Corridor Function	Natural Resource Subtotal	Public Access	Existing facilities	Community Access	Recreation Facilities Subtotal	Total Score	% Total Points	Rank
Cedar Creek	Confluence - Lively Park	8	7	8	7	30	7	6	5	6	24	5	6	7	6	8	32	2	2	2	6	92	58%	2
N. Cedar Creek	Lively Park – 75 th Street	8	7	7	8	30	5	4	4	4	17	4	7	5	3	5	24	4	3	3	10	81	51%	3
Cedar Creek	75 th Street – Thurston Road	7	6	6	7	26	8	6	4	6	24	5	7	2	6	4	24	3	2	2	7	81	51%	3
Cedar Creek	Hwy 126 - Headwaters	6	5	6	8	25	8	8	7	6	29	5	9	3	6	7	30	2	4	3	9	93	58%	1
Gray Creek	75th Street - UGB	6	5	4	4	19	6	3	5	4	18	5	5	3	4	4	21	4	3	4	11	69	43%	4
Gray Creek	UGB – Thurston Road	2	6	4	3	15	4	2	4	5	15	4	6	3	4	5	22	1	1	1	3	<u>55</u>	34%	8
Gay Creek	Hwy 126 - Headwaters	4	4	3	4	15	7	4	7	3	21	4	3	7	6	6	26	2	3	2	7	69	43%	4
75 th Street Channel	S. Cedar Creek – Hwy 126	2	6	4	4	16	4	3	4	4	15	4	3	2	3	3	15	2	2	3	7	53	33%	9
S. Cedar Creek	Lively Park – Mouth	7	6	5	6	24	6	4	4	5	19	4	6	8	5	4	27	3	3	4	10	80	50%	3
72 nd Street Channel	S. Cedar Creek – End of Channel	4	6	4	5	19	3	5	6	3	17	3	2	4	2	1	12	8	4	5	17	65	41%	5
69th Street Channel	S. Cedar Creek – End of Channel	2	6	3	3	14	4	2	2	3	11	2	2	4	2	1	11	7	4	4	15	51	32%	10
Blue Water Ponds (and Associated Waterways)		4	3	4	6	17	6	4	4	5	19	5	5	3	4	5	22	1	1	1	3	61	38%	6
Control Gates	Existing Flow Control Gate - Intake	4	4	3	5	16	6	2	5	4	17	3	4	5	4	6	22	2	1	2	5	60	38%	7



Waterway Name: Cedar Creek Date: 04/02/2007

Beginning At: Confluence Ending At: Lively Park

Waterway Scoring Summary

Cedar Creek: Confluence – Lively Park (R1 – R14)

Physical Assessment	Score	Possible	% of Total
		Score	Pts
Physical Characteristics	8	10	
Channel Stability - BANKS	7	10	
Channel Stability -BEDS	8	10	
Sediment	7	10	
Physical Subtotal	30	40	<i>7</i> 5%
Water Quality Assessment			
Absorption and/or Filtration of Pollutants	7	10	
Aeration	6	10	
Shade/Temperature Moderation	5	10	
Channel Bank Integrity and Protection	6	10	
Water Quality Subtotal	24	40	60%
Natural Resource Assessment			
Riparian Width	5	10	
Habitat Diversity	6	10	1
Percent Cover of Invasive Plant Species	7	10	1
Aquatic Habitat Structure	6	10	1
Wildlife Corridor Function	8	10	1
Natural Resource Subtotal	32	50	64%
Recreation Facilities Assessment			
Public Access	2	10	
Existing Facilities	2	10	
Community Served Through Access	2	10	
Recreation Facilities Subtotal	6	30	20%
WATERWAY ASSESSMENT TOTAL SCORE	92	160	58%

Average from previous Assessment: 6.8 (Fair)

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)

RATING	I
8	
	l

Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form	Channel has some Natural form	Closed or Lined channel
Channel Type fits Grade, Minor	returning.	No Natural features Creates
or no modifications, capacity		ecological problems.
contained		Modifications are failing, needs
		attention. Flooding occurs.
10	5	1

Channel Stability:

RATING	
7	

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

well protected and vegetated	Channel banks show sign of erosion, sloughing,	stream function impaired, needs
condition.	cracking	immediate attention.
10	5	1

RATING **8**

Measure: <u>Channel Stability -BEDS</u> will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

Channel beds are stable provide deposition and transport	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:



Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
10	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RATING
7

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid
completely covered	covered with	aquatic vegetation	of any aquatic
with aquatic	aquatic vegetation	in contact with	vegetation
vegetation in contact	in contact with	water during low	
with water during low	water during low	flow conditions	
flow conditions.	flow conditions		
10	7	3	1

Aeration:



Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles in streambed >75% of channel length and multiple sources of other turbulence producing features	Rocks and riffles in streambed >33% of channel length or multiple sources of other turbulence producing features	Channel segment has at least one feature that produces significant turbulence during low flow conditions	Channel segment is devoid of any turbulence producing features
10	7	3	1

Shade/Temperature Moderation

RATING **5** Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

segment is covered	within channel segment is covered	>25% of water area within channel segment is covered	No shade on water area at any time of day
by shade at midday	by shade at midday	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks or else sporadic patches of toes armoring	Bare soil on banks, no toe armoring along either bank
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
5

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
7

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated	25 -75% estimated	75-90% estimated	>90% estimated invasive cover
	invasive cover	invasive cover	invasive cover	
10	7	5	3	1

Aquatic habitat structure

RATING
6

Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

	Logs/large woody debris: Fallen trees or parts of trees that provide structure and attachment for aquatic macroinvertebrates & hiding places for fish.
	Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
	deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
	depth).
	Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
	over and covers the system surface, providing shade and cover.
	Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
_	more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
	Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
_	underwater pockets used by fish for hiding and protection.
	Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
	surface forming structure for invertebrate attachment and fish cover.
	Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
	thick enough to provide invertebrate attachment and fish cover.
	Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
_	current, and relatively shallow depth (usually less than 18 inches).
	Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
	side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

RATING 8	Measure: Waterways are often important migration corridors for wildlife moving within the watershed. This is particularly true of urban areas where most of the landscape is developed or fragmented. For this characteristic check one selection from each of the three categories below. Use this information to quantitatively assess the functionality of the reach for wildlife travel.							
	☐ Wide (>30 ft on one side) well-connected riparian corridor☐ Narrow (<30 feet on both sides) well-connected riparian corridor							
	 Continuous along entire reach Slightly fragmented by road crossings or passable barriers Substantially fragmented by unvegetated development or impassible barriers 							
	 Forested canopy along majority of the reach Shrub canopy along majority of the reach Unmanaged prairie or meadow along majority of reach Mowed turf or manicured shrub along majority reach. 							
	is wide and unbroken.	Corridor is slightly fragmented or	Corridor is highly fragmented and					
	of habitat provides good	narrow but provides substantial	narrow. It is mostly developed					
cover for	a wide range of animals.	protection for animal movement.	with little cover for animal movement.					
	10	5	1					

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

1	RA	7	II	٧G
		2	2	

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities

RATING
2

Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5	3	1

Community Served Through Access

RA	7	ΊN	G
	•	•	

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreational	Recreational	Recreational	Recreational	Recreational
facilities are accessible to and serve regional interests	facilities are accessible to and serve community interests	facilities are accessible to and serve neighborhood	facilities are not easily accessible but do serve limited local	facilities are not easily accessible or do not serve a valued public
12	_	interests	interests	interest
10	7	5	3	1

Waterway Name: **North Cedar Creek** Date: 04/02/2007

Beginning At: **Lively park** Ending At: **75**th **Street**

Waterway Scoring Summary

North Cedar Creek: Lively Park – 75th Street(R15 – R21)

Score	Possible	% of Total
	Score	Pts
8	10	
7	10	
7	10	
8	10	
30	40	<i>75%</i>
5	10	
4	10	
4	10	
4	10	
17	40	43%
4	10	
7	10	
5	10	
3	10	Ī
5	10	
24	50	48%
4	10	
3	10	
3	10	
10	30	33%
81	160	51%
	8 7 7 8 30 5 4 4 4 17 5 3 5 24	\$ 10 7 10 7 10 8 10 7 10 8 10 30 40 5 10 4 10 4 10 4 10 7 10 5 10 3 10 5 10 24 50 4 10 3 10 3 10 3 10 3 3 10

Average from previous Assessment: 7.0 (Fair)

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)

RATING
8

Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form	Channel has some Natural form	Closed or Lined channel
Channel Type fits Grade, Minor	returning.	No Natural features Creates
or no modifications, capacity		ecological problems.
contained		Modifications are failing, needs
		attention. Flooding occurs.
10	5	1

Channel Stability:

RATING
7

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

well protected and vegetated	Channel banks show sign of erosion, sloughing,	stream function impaired, needs
condition.	cracking	immediate attention.
10	5	1

RATING **7**

Measure: <u>Channel Stability -BEDS</u> will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:



Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
10	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RA	7	ING	
	!	5	

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid
completely covered	covered with	aquatic vegetation	of any aquatic
with aquatic	aquatic vegetation	in contact with	vegetation
vegetation in contact	in contact with	water during low	
with water during low	water during low	flow conditions	
flow conditions.	flow conditions		
10	7	3	1

Aeration:



Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles in streambed >75% of channel length and multiple sources of other turbulence producing features	Rocks and riffles in streambed >33% of channel length or multiple sources of other turbulence producing features	Channel segment has at least one feature that produces significant turbulence during low flow conditions	Channel segment is devoid of any turbulence producing features
10	7	3	1

Shade/Temperature Moderation



Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

Entire water area within channel	within channel		area at any time of
segment is covered by shade at midday	segment is covered by shade at midday	segment is covered by shade at midday	day
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks or else sporadic patches of toes	Bare soil on banks, no toe armoring along either bank
		patches of toes armoring	
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
4

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
5

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated invasive cover	25 -75% estimated invasive cover	75-90% estimated invasive cover	>90% estimated invasive cover
	11114401140 001401	11114401140 00101	111740170 00701	
10	7	5	3	1

Aquatic habitat structure

RATING
3

Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

Ш	Logs/large woody debris: Fallen trees or parts of trees that provide structure and attachment for
	aquatic macroinvertebrates & hiding places for fish.
	Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
	deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
	depth).
	Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
	over and covers the system surface, providing shade and cover.
	Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
	more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
	Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
	underwater pockets used by fish for hiding and protection.
	Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
	surface forming structure for invertebrate attachment and fish cover.
	Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
	thick enough to provide invertebrate attachment and fish cover.
	Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
	current, and relatively shallow depth (usually less than 18 inches).
П	Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
	side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

RATING 5	Measure: Waterways are often important migration corridors for wildlife moving within the watershed. This is particularly true of urban areas where most of the landscape is developed or fragmented. For this characteristic check one selection from each of the three categories below. Use this information to quantitatively assess the functionality of the reach for wildlife travel.				
	•	e) well-connected riparian corridor sides) well-connected riparian corri	dor		
	 Continuous along entire reach Slightly fragmented by road crossings or passable barriers Substantially fragmented by unvegetated development or impassible barriers 				
	 ☐ Forested canopy along majority of the reach ☐ Shrub canopy along majority of the reach ☐ Unmanaged prairie or meadow along majority of reach ☐ Mowed turf or manicured shrub along majority reach. 				
	is wide and unbroken.	Corridor is slightly fragmented or	Corridor is highly fragmented and		
	of habitat provides good	narrow but provides substantial	narrow. It is mostly developed		
cover for	a wide range of animals.	protection for animal movement.	with little cover for animal		
	10		movement.		
1	10	5			

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RATING
4

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities

RATING
3

Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5	1 3	1

Community Served Through Access

RA	TING
	3

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreation	onal	Recreational	Recreational	Recreational	Recreational
facilities		facilities are	facilities are	facilities are not	facilities are not
accessible		accessible to and serve community	accessible to and serve	easily accessible but do serve	easily accessible or do not serve a
serve reg		interests	neighborhood	limited local	valued public
			interests	interests	interest
1	0	7	5	3	1

Waterway Name: **Cedar Creek** Date: 04/02/2007

Beginning At: South Cedar Creek Ending At: Intake

Waterway Scoring Summary

Cedar Creek: South Cedar Creek - Intake (R22 - R37)

Physical Assessment	Score	Possible	% of Total
, nyoroan nisosoonnonn	333.3	Score	Pts
Physical Characteristics	7	10	
Channel Stability - BANKS	6	10	
Channel Stability -BEDS	6	10	
Sediment	7	10	
Physical Subtotal	25	40	63%
Water Quality Assessment			
Absorption and/or Filtration of Pollutants	8	10	
Aeration	6	10	
Shade/Temperature Moderation	4	10	
Channel Bank Integrity and Protection	6	10	
Water Quality Subtotal	24	40	60%
Natural Resource Assessment			
Riparian Width	5	10	
Habitat Diversity	7	10	
Percent Cover of Invasive Plant Species	2	10	
Aquatic Habitat Structure	6	10	
Wildlife Corridor Function	4	10	
Natural Resource Subtotal	24	50	48%
Recreation Facilities Assessment			
Public Access	3	10	
Existing Facilities	2	10	
Community Served Through Access	2	10	
Recreation Facilities Subtotal	7	30	23%
WATERWAY ASSESSMENT TOTAL SCORE	80	160	50%

Average from previous Assessment: 6.6 (Fair)

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)

RATING	
7	

Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form Channel Type fits Grade, Minor or no modifications, capacity contained	Channel has some Natural form returning.	Closed or Lined channel No Natural features Creates ecological problems. Modifications are failing, needs attention. Flooding occurs.
10	5	1

Channel Stability:

RATING	
6	

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

Channel banks are in stable, well protected and vegetated	erosion, sloughing,	Channel banks seriously eroded; stream function impaired, needs
condition.	cracking	immediate attention.
10	5	1

RATING **6**

Measure: Channel Stability -BEDS will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:



Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
l 10 l	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RA	TING
	8

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid
completely covered	covered with	aquatic vegetation	of any aquatic
with aquatic	aquatic vegetation	in contact with	vegetation
vegetation in contact	in contact with	water during low	
with water during low	water during low	flow conditions	
flow conditions.	flow conditions		
10	7	3	1

Aeration:

RATING	
6	

Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles in streambed >75% of channel length and multiple sources of other turbulence producing features	Rocks and riffles in streambed >33% of channel length or multiple sources of other turbulence producing features	Channel segment has at least one feature that produces significant turbulence during low flow conditions	Channel segment is devoid of any turbulence producing features
10	7	3	1

Shade/Temperature Moderation



Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

segment is covered	within channel segment is covered	>25% of water area within channel segment is covered	No shade on water area at any time of day
by shade at midday	by shade at midday	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks	Bare soil on banks, no toe armoring along either bank
		or else sporadic patches of toes armoring	
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
5

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
2

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated	25 -75% estimated	75-90% estimated	>90% estimated invasive cover
	invasive cover	invasive cover	invasive cover	
10	7	5	3	1

Aquatic habitat structure

RATING
6

Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

	Logs/large woody debris: Fallen trees or parts of trees that provide structure and attachment for aquatic macroinvertebrates & hiding places for fish.
	Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
	deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
	depth).
	Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
	over and covers the system surface, providing shade and cover.
	Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
_	more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
	Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
_	underwater pockets used by fish for hiding and protection.
	Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
	surface forming structure for invertebrate attachment and fish cover.
	Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
	thick enough to provide invertebrate attachment and fish cover.
	Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
_	current, and relatively shallow depth (usually less than 18 inches).
	Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
	side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

1	RATING 4	woodoro. Waterways are often important inigration corrects for whether moving within the					
	☐ Wide (>30 ft on one side) well-connected riparian corridor☐ Narrow (<30 feet on both sides) well-connected riparian corridor						
	 Continuous along entire reach Slightly fragmented by road crossings or passable barriers Substantially fragmented by unvegetated development or impassible barriers 						
	 Forested canopy along majority of the reach Shrub canopy along majority of the reach Unmanaged prairie or meadow along majority of reach Mowed turf or manicured shrub along majority reach. 						
	Corridor is wide and unbroken. Corridor is slightly fragmented or Corridor is highly fragmented and						
	-	of habitat provides good a wide range of animals.	narrow but provides substantial protection for animal movement.	narrow. It is mostly developed with little cover for animal			
				movement.			
ĺ		10	5	1			

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RA	7	11	۷G
	1	3	

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities

RATING
2

Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5	3	1

Community Served Through Access

RA	7	ΊN	G
	•	•	

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreation	onal	Recreational	Recreational	Recreational	Recreational
facilities		facilities are	facilities are	facilities are not	facilities are not
accessible		accessible to and serve community	accessible to and serve	easily accessible but do serve	easily accessible or do not serve a
serve reg		interests	neighborhood	limited local	valued public
			interests	interests	interest
1	0	7	5	3	1

Waterway Name: **Cedar Creek** Date: 04/02/2007

Beginning At: **Highway 126** Ending At: **Headwaters**

Waterway Scoring Summary

Cedar Creek: Hwy 126 - Headwaters (R38 - R41)

Score		% of Total
	Score	Pts
6	10	
5	10	
6	10	
8	10	
25	40	63%
8	10	
8	10	
7	10	
6	10	
29	40	73%
5	10	
9	10	
3	10	
6	10	
7	10	
30	50	60%
2	10	
4	10	1
3	10	
9	30	30%
93	160	58%
	6 5 6 8 25 8 8 7 6 29 5 9 3 6 7 30 2 4 3 9	Score 6 10 5 10 6 10 8 10 25 40 8 10 7 10 6 10 29 40 5 10 9 10 3 10 6 10 7 10 30 50 2 10 4 10 3 10 9 30

Average from previous Assessment: 6.7 (Fair)

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)

RATING	l	
6		
	I	

Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form Channel Type fits Grade, Minor or no modifications, capacity contained	Channel has some Natural form returning.	Closed or Lined channel No Natural features Creates ecological problems. Modifications are failing, needs attention. Flooding occurs.
10	5	1

Channel Stability:

RATING					
5					

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

Channel banks are in stable, well protected and vegetated condition.	Channel banks show sign of erosion, sloughing, cracking	Channel banks seriously eroded; stream function impaired, needs immediate attention.
10	5	1

RATING **6**

Measure: <u>Channel Stability -BEDS</u> will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:



Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
10	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RA	7	ING
	8	3

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid
completely covered	covered with	aquatic vegetation	of any aquatic
with aquatic	aquatic vegetation	in contact with	vegetation
vegetation in contact	in contact with	water during low	
with water during low	water during low	flow conditions	
flow conditions.	flow conditions		
10	7	3	1

Aeration:



Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles in streambed >75% of channel length and multiple sources of other turbulence producing features	Rocks and riffles in streambed >33% of channel length or multiple sources of other turbulence producing features	Channel segment has at least one feature that produces significant turbulence during low flow conditions	Channel segment is devoid of any turbulence producing features
10	7	3	1

Shade/Temperature Moderation

RATING
7

Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

segment is covered	within channel segment is covered	>25% of water area within channel segment is covered	No shade on water area at any time of day
by shade at midday	by shade at midday	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks or else sporadic patches of toes	Bare soil on banks, no toe armoring along either bank
		patches of toes armoring	
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
5

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
3

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated	25 -75% estimated	75-90% estimated	>90% estimated invasive cover
	invasive cover	invasive cover	invasive cover	
10	7	5	3	1

Aquatic habitat structure

RATING
6

Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

Logs/large woody debris: Fallen trees or parts of trees that provide structure and attachment for aquatic macroinvertebrates & hiding places for fish.
Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
depth).
Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
over and covers the system surface, providing shade and cover.
Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
 underwater pockets used by fish for hiding and protection.
Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
 surface forming structure for invertebrate attachment and fish cover.
Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
 thick enough to provide invertebrate attachment and fish cover.
Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
 current, and relatively shallow depth (usually less than 18 inches).
Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

RATING 7	Measure: Waterways are often important migration corridors for wildlife moving within the watershed. This is particularly true of urban areas where most of the landscape is developed or fragmented. For this characteristic check one selection from each of the three categories below. Use this information to quantitatively assess the functionality of the reach for wildlife travel.						
☐ Wide (>30 ft on one side) well-connected riparian corridor☐ Narrow (<30 feet on both sides) well-connected riparian corridor							
 Continuous along entire reach Slightly fragmented by road crossings or passable barriers Substantially fragmented by unvegetated development or impassible barriers 							
 Forested canopy along majority of the reach Shrub canopy along majority of the reach Unmanaged prairie or meadow along majority of reach Mowed turf or manicured shrub along majority reach. 							
Diversity	s wide and unbroken. of habitat provides good a wide range of animals.	Corridor is slightly fragmented or narrow but provides substantial protection for animal movement.	Corridor is highly fragmented and narrow. It is mostly developed with little cover for animal				
	movement.						

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RA	7	11	۷G
	2	2	

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities



Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5	3	1

Community Served Through Access

RA	TING	
	2	

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreational	Recreational	Recreational	Recreational	Recreational
facilities are accessible to and serve regional interests	facilities are accessible to and serve community interests	facilities are accessible to and serve neighborhood interests	facilities are not easily accessible but do serve limited local interests	facilities are not easily accessible or do not serve a valued public interest
10	7	5	3	1

Waterway Name: **Gray Creek** Date: 04/02/2007

Beginning At: **75**th **Street** Ending At: **UGB**

Waterway Scoring Summary

Gray Creek: 75th Street – UGB (R1 – R4)

Physical Assessment	Score	Possible	% of Total
Physical Assessment	Score	Score	% of Total
Physical Characteristics	6	10	rts
Channel Stability - BANKS	5	10	ł
Channel Stability -BEDS	4	10	
Sediment	4	10	1
Physical Subtotal	19	40	48%
Water Quality Assessment			
Absorption and/or Filtration of Pollutants	6	10	
Aeration	3	10]
Shade/Temperature Moderation	5	10	
Channel Bank Integrity and Protection	4	10	
Water Quality Subtotal	18	40	45%
Natural Resource Assessment			
Riparian Width	5	10	
Habitat Diversity	5	10	
Percent Cover of Invasive Plant Species	3	10	1
Aquatic Habitat Structure	4	10	
Wildlife Corridor Function	4	10	
Natural Resource Subtotal	21	50	42%
Recreation Facilities Assessment			
Public Access	4	10	
Existing Facilities	3	10	
Community Served Through Access	4	10	
Recreation Facilities Subtotal	11	30	37%
WATERWAY ASSESSMENT TOTAL SCORE	69	160	43%

Average from previous Assessment: 6.5 (Fair)

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)

RATING
6

Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form Channel Type fits Grade, Minor or no modifications, capacity contained	Channel has some Natural form returning.	Closed or Lined channel No Natural features Creates ecological problems. Modifications are failing, needs attention. Flooding occurs.
10	5	1

Channel Stability:

RATING
5

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

Channel banks are in stable, well protected and vegetated condition.	Channel banks show sign of erosion, sloughing, cracking	Channel banks seriously eroded; stream function impaired, needs immediate attention.
10	5	1

RATING

4

Measure: Channel Stability -BEDS will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

Channel beds are stable provide deposition and transport	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:



Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
l 10 l	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RA	7	ING
	ť	3

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid
completely covered	covered with	aquatic vegetation	of any aquatic
with aquatic	aquatic vegetation	in contact with	vegetation
vegetation in contact	in contact with	water during low	
with water during low	water during low	flow conditions	
flow conditions.	flow conditions		
10	7	3	1

Aeration:



Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles in streambed >75% of channel length and multiple sources of other turbulence producing features	Rocks and riffles in streambed >33% of channel length or multiple sources of other turbulence producing features	Channel segment has at least one feature that produces significant turbulence during low flow conditions	Channel segment is devoid of any turbulence producing features
10	7	3	1

Shade/Temperature Moderation

RATING 5 Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

Entire water area within channel segment is covered	within channel	>25% of water area within channel segment is covered	No shade on water area at any time of day
by shade at midday	, •	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks or else sporadic patches of toes	Bare soil on banks, no toe armoring along either bank
		patches of toes armoring	
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING	i
5	

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity

RATING	
5	

Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
3

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated	25 -75% estimated	75-90% estimated	>90% estimated invasive cover
	invasive cover	invasive cover	invasive cover	
10	7	5	3	1

Aquatic habitat structure



Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

	Logs/large woody debris: Fallen trees or parts of trees that provide structure and attachment for aquatic macroinvertebrates & hiding places for fish.
	Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
	deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
	depth).
	Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
	over and covers the system surface, providing shade and cover.
	Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
_	more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
	Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
_	underwater pockets used by fish for hiding and protection.
	Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
	surface forming structure for invertebrate attachment and fish cover.
	Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
	thick enough to provide invertebrate attachment and fish cover.
	Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
_	current, and relatively shallow depth (usually less than 18 inches).
	Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
	side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

RATING 4	woodard: Waterways are often important inigration confidence for whater moving within the						
	☐ Wide (>30 ft on one side) well-connected riparian corridor☐ Narrow (<30 feet on both sides) well-connected riparian corridor						
	 Continuous along entire reach Slightly fragmented by road crossings or passable barriers Substantially fragmented by unvegetated development or impassible barriers 						
	 ☐ Forested canopy along majority of the reach ☐ Shrub canopy along majority of the reach ☐ Unmanaged prairie or meadow along majority of reach ☐ Mowed turf or manicured shrub along majority reach. 						
	Corridor is wide and unbroken. Corridor is slightly fragmented or Corridor is highly fragmented and						
•	of habitat provides good a wide range of animals.	narrow but provides substantial protection for animal movement.	narrow. It is mostly developed with little cover for animal movement.				
	10	5	1				

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RATING
4

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities



Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5] 3	1

Community Served Through Access

RATING	
4	

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreational	Recreational	Recreational	Recreational	Recreational
facilities are accessible to and serve regional interests	facilities are accessible to and serve community interests	facilities are accessible to and serve neighborhood	facilities are not easily accessible but do serve limited local	facilities are not easily accessible or do not serve a valued public
12	_	interests	interests	interest
10	7	5	3	1

Waterway Name: **Gray Creek** Date: 04/02/2007

Beginning At: **UGB** Ending At: **Thurston Road**

Waterway Scoring Summary

Gray Creek: UGB - Thurston Road (R5 - R9)

Physical Assessment	Score	Possible Score	% of Total Pts
Physical Characteristics	2	10	
Channel Stability - BANKS	6	10	
Channel Stability -BEDS	4	10	
Sediment	3	10	
Physical Subtotal	15	40	38%
Water Quality Assessment			
Absorption and/or Filtration of Pollutants	4	10	
Aeration	2	10	
Shade/Temperature Moderation	4	10	
Channel Bank Integrity and Protection	5	10	
Water Quality Subtotal	15	40	38%
Natural Resource Assessment			
Riparian Width	4	10	
Habitat Diversity	6	10	
Percent Cover of Invasive Plant Species	3	10	
Aquatic Habitat Structure	4	10	
Wildlife Corridor Function	5	10	
Natural Resource Subtotal	22	50	44%
Recreation Facilities Assessment			
Public Access	1	10	
Existing Facilities	1	10	
Community Served Through Access	1	10	
Recreation Facilities Subtotal	3	30	10%
WATERWAY ASSESSMENT TOTAL SCORE	55	160	34%

Average from previous Assessment: 5.0 (Poor)

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)

RATING	
2	
	l

Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form	Channel has some Natural form	Closed or Lined channel
Channel Type fits Grade, Minor	returning.	No Natural features Creates
or no modifications, capacity		ecological problems.
contained		Modifications are failing, needs
		attention. Flooding occurs.
10	5	1

Channel Stability:

RATING	
6	

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

Channel banks are in stable, well protected and vegetated	Channel banks show sign of erosion, sloughing,	Channel banks seriously eroded; stream function impaired, needs
condition.	cracking	immediate attention.
10	5	1

RATING

4

Measure: Channel Stability -BEDS will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

Channel beds are stable provide deposition and transport	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:

RATING	
3	I
	I
	I

Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
10	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RATING	
4	

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid
completely covered	covered with	aquatic vegetation	of any aquatic
with aquatic	aquatic vegetation	in contact with	vegetation
vegetation in contact	in contact with	water during low	
with water during low	water during low	flow conditions	
flow conditions.	flow conditions		
10	7	3	1

Aeration:



Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles in streambed >75% of channel length and multiple sources of other turbulence producing features	Rocks and riffles in streambed >33% of channel length or multiple sources of other turbulence producing features	Channel segment has at least one feature that produces significant turbulence during low flow conditions	Channel segment is devoid of any turbulence producing features
10	7	3	1

Shade/Temperature Moderation



Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

segment is covered	within channel segment is covered	>25% of water area within channel segment is covered	No shade on water area at any time of day
by shade at midday	by shade at midday	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks or else sporadic patches of toes	Bare soil on banks, no toe armoring along either bank
		patches of toes armoring	
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
4

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
3

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated	25 -75% estimated	75-90% estimated	>90% estimated invasive cover
	invasive cover	invasive cover	invasive cover	
10	7	5	3	1

Aquatic habitat structure



Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

	Logs/large woody debris: Fallen trees or parts of trees that provide structure and attachment for aquatic macroinvertebrates & hiding places for fish.
	Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
	deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
	depth).
	Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
	over and covers the system surface, providing shade and cover.
	Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
_	more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
	Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
_	underwater pockets used by fish for hiding and protection.
	Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
	surface forming structure for invertebrate attachment and fish cover.
	Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
	thick enough to provide invertebrate attachment and fish cover.
	Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
_	current, and relatively shallow depth (usually less than 18 inches).
	Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
	side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

	Measure: Waterways are often important migration corridors for wildlife moving within the watershed. This is particularly true of urban areas where most of the landscape is developed or fragmented. For this characteristic check one selection from each of the three categories below. Use this information to quantitatively assess the functionality of the reach for wildlift							
	travel. Wide (>30 ft on one side) well-connected riparian corridor Narrow (<30 feet on both sides) well-connected riparian corridor							
			reach ad crossings or passable barriers by unvegetated development or imp	passible barriers				
	Forested canopy along majority of the reach Shrub canopy along majority of the reach Unmanaged prairie or meadow along majority of reach Mowed turf or manicured shrub along majority reach.							
Corridor is wide and unbroken. Diversity of habitat provides good cover for a wide range of animals.		of habitat provides good	Corridor is slightly fragmented or narrow but provides substantial protection for animal movement.	Corridor is highly fragmented and narrow. It is mostly developed with little cover for animal movement.				
		1						

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RATING
1

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities



Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5] 3	1

Community Served Through Access

RATING	
1	

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreational	Recreational	Recreational	Recreational	Recreational
facilities are accessible to and	facilities are accessible to and	facilities are accessible to and	facilities are not easily accessible	facilities are not easily accessible
serve regional	serve community	serve	but do serve	or do not serve a
interests	interests	neighborhood interests	limited local interests	valued public interest
10	7	5	3	1

Waterway Name: **Gay Creek** Date: 04/02/2007

Beginning At: **Main Street** Ending At: **Headwaters**

Waterway Scoring Summary

Gay Creek: Main Street – Headwaters (R6 – Headwaters)

Physical Assessment	Score	Possible	% of Total
		Score	Pts
Physical Characteristics	4	10	
Channel Stability - BANKS	4	10	
Channel Stability -BEDS	3	10	
Sediment	4	10	
Physical Subtotal	15	40	38%
Water Quality Assessment			
Absorption and/or Filtration of Pollutants	7	10	
Aeration	4	10	
Shade/Temperature Moderation	7	10	
Channel Bank Integrity and Protection	3	10	
Water Quality Subtotal	21	40	53%
Natural Resource Assessment			
Riparian Width	4	10	
Habitat Diversity	3	10	
Percent Cover of Invasive Plant Species	7	10	
Aquatic Habitat Structure	6	10	
Wildlife Corridor Function	6	10	
Natural Resource Subtotal	26	50	52%
Recreation Facilities Assessment			
Public Access	2	10	
Existing Facilities	3	10	
Community Served Through Access	2	10	
Recreation Facilities Subtotal	7	30	23%
WATERWAY ASSESSMENT TOTAL SCORE	69	160	43%

Average from previous Assessment: 6.8 (Fair)

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)

RATING	
4	

Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form Channel Type fits Grade, Minor or no modifications, capacity contained	Channel has some Natural form returning.	Closed or Lined channel No Natural features Creates ecological problems. Modifications are failing, needs attention. Flooding occurs.
10	5	1

Channel Stability:

RATING	
3	

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

Channel banks are in stable, well protected and vegetated	erosion, sloughing,	Channel banks seriously eroded; stream function impaired, needs	
condition.	cracking	immediate attention.	
10	5	1	

RATING

4

Measure: Channel Stability -BEDS will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:



Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
10	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RATING
7

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid
completely covered	covered with	aquatic vegetation	of any aquatic
with aquatic	aquatic vegetation	in contact with	vegetation
vegetation in contact	in contact with	water during low	
with water during low	water during low	flow conditions	
flow conditions.	flow conditions		
10	7	3	1

Aeration:



Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles in streambed >75% of channel length and multiple sources of other turbulence producing features	Rocks and riffles in streambed >33% of channel length or multiple sources of other turbulence producing features	Channel segment has at least one feature that produces significant turbulence during low flow conditions	Channel segment is devoid of any turbulence producing features
10	7	3	1

Shade/Temperature Moderation

RATING
7

Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

Entire water area within channel segment is covered	within channel segment is covered	>25% of water area within channel segment is covered	No shade on water area at any time of day
by shade at midday	by shade at midday	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks or else sporadic patches of toes	Bare soil on banks, no toe armoring along either bank
		patches of toes armoring	
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
4

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
2

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated	25 -75% estimated	75-90% estimated	>90% estimated invasive cover
	invasive cover	invasive cover	invasive cover	
10	7	5	3	1

Aquatic habitat structure

RATING
6

Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

	Logs/large woody debris: Fallen trees or parts of trees that provide structure and attachment for aquatic macroinvertebrates & hiding places for fish.
	Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
	deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
	depth).
	Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
	over and covers the system surface, providing shade and cover.
	Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
	more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
	Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
_	underwater pockets used by fish for hiding and protection.
	Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
_	surface forming structure for invertebrate attachment and fish cover.
	Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
	thick enough to provide invertebrate attachment and fish cover.
	Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
_	current, and relatively shallow depth (usually less than 18 inches).
	Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
	side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

RATING	Measure: Waterways are often important migration corridors for wildlife moving within the							
6	watershed. This is particularly true of urban areas where most of the landscape is developed or fragmented. For this characteristic check one selection from each of the three categories below. Use this information to quantitatively assess the functionality of the reach for wildlife							
	travel. Wide (>30 ft on one side) well-connected riparian corridor Narrow (<30 feet on both sides) well-connected riparian corridor							
	 Continuous along entire reach Slightly fragmented by road crossings or passable barriers Substantially fragmented by unvegetated development or impassible barriers 							
	 ☐ Forested canopy along majority of the reach ☐ Shrub canopy along majority of the reach ☐ Unmanaged prairie or meadow along majority of reach ☐ Mowed turf or manicured shrub along majority reach. 							
	is wide and unbroken.	Corridor is slightly fragmented or	Corridor is highly fragmented and					
	of habitat provides good	narrow but provides substantial	narrow. It is mostly developed					
cover for	a wide range of animals.	protection for animal movement.	with little cover for animal movement.					
	10	5	1					

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RA	7	11	٧G	
	2	2		

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities

R	ATING
	3

Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5	3	1

Community Served Through Access

RA	7	ΊN	G	
2				

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreational	Recreational	Recreational	Recreational	Recreational
facilities are accessible to and	facilities are accessible to and	facilities are accessible to and	facilities are not easily accessible	facilities are not easily accessible
serve regional	serve community	serve	but do serve	or do not serve a
interests	interests	neighborhood interests	limited local interests	valued public interest
10	7	5	3	1

Waterway Name: **75**th **Street Channel** Date: 04/02/2007

Beginning At: **South Cedar Creek** Ending At: **Main Street**

Waterway Scoring Summary

75th Street Channel: South Cedar Creek – Main Street (R1 – R5)

75" Street Channel: South Cedar Creek –			
Physical Assessment	Score	Possible	% of Tota
		Score	Pts
Physical Characteristics	2	10	
Channel Stability - BANKS	6	10	
Channel Stability -BEDS	4	10	
Sediment	4	10	
Physical Subtotal	16	40	40%
Water Quality Assessment			
Absorption and/or Filtration of Pollutants	4	10	
Aeration	3	10	
Shade/Temperature Moderation	4	10	
Channel Bank Integrity and Protection	4	10	
Water Quality Subtotal	15	40	38%
Natural Resource Assessment			
Riparian Width	4	10	
Habitat Diversity	3	10	
Percent Cover of Invasive Plant Species	2	10	
Aquatic Habitat Structure	3	10	
Wildlife Corridor Function	3	10	
Natural Resource Subtotal	15	50	30%
Recreation Facilities Assessment			
Public Access	2	10	
Existing Facilities	2	10	
Community Served Through Access	3	10	
Recreation Facilities Subtotal	7	30	23%
WATERWAY ASSESSMENT TOTAL SCORE	53	160	33%

Average from previous Assessment: 6.3 (Fair)

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)

RATING	
2	1
	I
	۱

Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form	Channel has some Natural form	Closed or Lined channel
Channel Type fits Grade, Minor	returning.	No Natural features Creates
or no modifications, capacity		ecological problems.
contained		Modifications are failing, needs
		attention. Flooding occurs.
10	5	1

Channel Stability:

RATING
6

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

Channel banks are in stable, well protected and vegetated	Channel banks show sign of erosion, sloughing,	Channel banks seriously eroded; stream function impaired, needs	
condition.	cracking	immediate attention.	
10	5	1	

RATING

4

Measure: Channel Stability -BEDS will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

Channel beds are stable provide deposition and transport	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:



Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities		Sediment values		Sediment volume is either
are stable. Provide		seem unbalanced.		heavy or non-existent. Bed
balanced deposition		Stream function		and bank are altered
and transport, creates good environmental conditions		seems stable. Sediment problems during specific events.		because of extreme sediment conditions. Toxicity is present
10	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RATING	
4	

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid
completely covered	covered with	aquatic vegetation	of any aquatic
with aquatic	aquatic vegetation	in contact with	vegetation
vegetation in contact	in contact with	water during low	
with water during low	water during low	flow conditions	
flow conditions.	flow conditions		
10	7	3	1

Aeration:



Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles in streambed >75% of channel length and multiple sources of other turbulence producing features	Rocks and riffles in streambed >33% of channel length or multiple sources of other turbulence producing features	Channel segment has at least one feature that produces significant turbulence during low flow conditions	Channel segment is devoid of any turbulence producing features
10	7	3	1

Shade/Temperature Moderation



Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

Entire water area within channel segment is covered	within channel	>25% of water area within channel segment is covered	No shade on water area at any time of day
by shade at midday	, •	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks or else sporadic patches of toes	Bare soil on banks, no toe armoring along either bank
		patches of toes armoring	
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
4

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
2

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated invasive cover	25 -75% estimated invasive cover	75-90% estimated invasive cover	>90% estimated invasive cover
	11114401140 001401	11114401140 00101	111740170 00701	
10	7	5	3	1

Aquatic habitat structure

RATING
3

Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

	Logs/large woody debris: Fallen trees or parts of trees that provide structure and attachment for
	aquatic macroinvertebrates & hiding places for fish.
	Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
	deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
	depth).
	Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
	over and covers the system surface, providing shade and cover.
	Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
	more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
	Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
	underwater pockets used by fish for hiding and protection.
	Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
	surface forming structure for invertebrate attachment and fish cover.
	Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
	thick enough to provide invertebrate attachment and fish cover.
	Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
_	current, and relatively shallow depth (usually less than 18 inches).
П	Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
	side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

Measure: Waterways are often important migration corridors for wildlife moving within the watershed. This is particularly true of urban areas where most of the landscape is developed or fragmented. For this characteristic check one selection from each of the three categories below. Use this information to quantitatively assess the functionality of the reach for wildlife travel.						
 ☐ Wide (>30 ft on one side) well-connected riparian corridor ☐ Narrow (<30 feet on both sides) well-connected riparian corridor 						
 Continuous along entire reach Slightly fragmented by road crossings or passable barriers Substantially fragmented by unvegetated development or impassible barriers 						
 Forested canopy along majority of the reach Shrub canopy along majority of the reach Unmanaged prairie or meadow along majority of reach Mowed turf or manicured shrub along majority reach. 						
Diversity	s wide and unbroken. of habitat provides good a wide range of animals.	Corridor is slightly fragmented or narrow but provides substantial protection for animal movement.	Corridor is highly fragmented and narrow. It is mostly developed with little cover for animal movement.			
	10	5	1			

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RA	7	11	٧G
	2	2	

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities

RATING
2

Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5	3	1

Community Served Through Access

RA	T	ING
	1	2

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreational	Recreational	Recreational	Recreational	Recreational	
facilities are	facilities are	facilities are	facilities are not	facilities are not	
accessible to and	accessible to and	accessible to and	easily accessible	easily accessible	
serve regional	serve community	serve	but do serve	or do not serve a	
interests	interests	neighborhood	limited local	valued public	
		interests	interests	interest	
10	7	5	3	1	

Waterway Name: **South Cedar Creek** Date: 04/02/2007

Beginning At: Lively Park Ending At: Mouth

Waterway Scoring Summary

South Cedar Creek: Lively Park - Mouth (R1 - R11)

Physical Assessment	Score	Possible	% of Total
		Score	Pts
Physical Characteristics	7	10	
Channel Stability - BANKS	6	10	1
Channel Stability -BEDS	5	10	
Sediment	6	10	
Physical Subtotal	24	40	60%
Water Quality Assessment			
Absorption and/or Filtration of Pollutants	6	10	
Aeration	4	10	
Shade/Temperature Moderation	4	10	
Channel Bank Integrity and Protection	5	10	
Water Quality Subtotal	19	40	48%
Natural Resource Assessment			
Riparian Width	4	10	
Habitat Diversity	6	10	
Percent Cover of Invasive Plant Species	8	10	
Aquatic Habitat Structure	5	10	
Wildlife Corridor Function	4	10	
Natural Resource Subtotal	27	50	54%
Recreation Facilities Assessment			
Public Access	3	10	
Existing Facilities	3	10	
Community Served Through Access	4	10	
Recreation Facilities Subtotal	10	30	33%
WATERWAY ASSESSMENT TOTAL SCORE	80	160	50%

Average from previous Assessment: 6.0 (Poor)

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)

RATING
7

Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form Channel Type fits Grade, Minor or no modifications, capacity contained	Channel has some Natural form returning.	Closed or Lined channel No Natural features Creates ecological problems. Modifications are failing, needs attention. Flooding occurs.
10	5	1

Channel Stability:

RATING	
6	

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

Channel banks are in stable, well protected and vegetated	erosion, sloughing,	Channel banks seriously eroded; stream function impaired, needs
condition.	cracking	immediate attention.
10	5	1

RATING

5

Measure: Channel Stability -BEDS will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

Channel beds are stable provide deposition and transport	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:

RATING
6

Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
10	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RATING	
6	

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid
completely covered	covered with	aquatic vegetation	of any aquatic
with aquatic	aquatic vegetation	in contact with	vegetation
vegetation in contact	in contact with	water during low	
with water during low	water during low	flow conditions	
flow conditions.	flow conditions		
10	7	3	1

Aeration:



Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles in streambed >75% of channel length and multiple sources of other turbulence producing features	Rocks and riffles in streambed >33% of channel length or multiple sources of other turbulence producing features	Channel segment has at least one feature that produces significant turbulence during low flow conditions	Channel segment is devoid of any turbulence producing features
10	7	3	1

Shade/Temperature Moderation



Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

Entire water area within channel	within channel		area at any time of
segment is covered	segment is covered	segment is covered	day
by shade at midday	by shade at midday	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks or else sporadic patches of toes	Bare soil on banks, no toe armoring along either bank
		patches of toes armoring	
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
4

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
8

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated	25 -75% estimated	75-90% estimated	>90% estimated invasive cover
	invasive cover	invasive cover	invasive cover	
10	7	5	3	1

Aquatic habitat structure

RATING
5

Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

Ш	Logs/large woody debris: Fallen trees of parts of trees that provide structure and attachment for
	aquatic macroinvertebrates & hiding places for fish.
	Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
	deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
	depth).
	Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
	over and covers the system surface, providing shade and cover.
	Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
	more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
	Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
	underwater pockets used by fish for hiding and protection.
	Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
	surface forming structure for invertebrate attachment and fish cover.
	Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
	thick enough to provide invertebrate attachment and fish cover.
	Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
	current, and relatively shallow depth (usually less than 18 inches).
	Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
	side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

RATING 4	woodd, c. water ways are often important inigration confidence for whether moving within the					
		e) well-connected riparian corridor sides) well-connected riparian corri	dor			
	 Continuous along entire reach Slightly fragmented by road crossings or passable barriers Substantially fragmented by unvegetated development or impassible barriers 					
 ☐ Forested canopy along majority of the reach ☐ Shrub canopy along majority of the reach ☐ Unmanaged prairie or meadow along majority of reach ☐ Mowed turf or manicured shrub along majority reach. 						
Diversity	is wide and unbroken. of habitat provides good a wide range of animals.	Corridor is slightly fragmented or narrow but provides substantial protection for animal movement.	Corridor is highly fragmented and narrow. It is mostly developed with little cover for animal movement.			
	10	5	1			

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RA	7	11	۷G
	1	3	

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities

RATIN	G
3	
3	

Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5	3	1

Community Served Through Access

RATING	
4	

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreation	onal	Recreational	Recreational	Recreational	Recreational
facilities		facilities are	facilities are	facilities are not	facilities are not
accessible		accessible to and serve community	accessible to and serve	easily accessible but do serve	easily accessible or do not serve a
serve reg		interests	neighborhood	limited local	valued public
			interests	interests	interest
1	0	7	5	3	1

Waterway Name: **72nd Street Channel** Date: 04/02/2007

Beginning At: Confluence with S. Cedar Creek Ending At: End of Channel

Waterway Scoring Summary

72nd Street Channel: Confluence with S. Cedar Creek – End of Channel (New)

12 Sheet Chainlei. Connuence with 5. Co	tual Citter		Chambel (i
Physical Characteristics	4	10]
Channel Stability - BANKS	6	10	1
Channel Stability -BEDS	4	10	1
Sediment	5	10	
Physical Subtotal	19	40	48%
Water Quality Assessment			
Absorption and/or Filtration of Pollutants	3	10	
Aeration	5	10	
Shade/Temperature Moderation	6	10	
Channel Bank Integrity and Protection	3	10	
Water Quality Subtotal	17	40	43%
Natural Resource Assessment			
Riparian Width	3	10	
Habitat Diversity	2	10	1
Percent Cover of Invasive Plant Species	4	10	1
Aquatic Habitat Structure	2	10	
Wildlife Corridor Function	1	10	1
Natural Resource Subtotal	12	50	24%
Recreation Facilities Assessment			
Public Access	8	10	
Existing Facilities	4	10]
Community Served Through Access	5	10	
Recreation Facilities Subtotal	17	30	57%
WATERWAY ASSESSMENT TOTAL SCORE	65	160	41%

Average from previous Assessment: N/A

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)



Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form Channel Type fits Grade, Minor or no modifications, capacity contained	Channel has some Natural form returning.	Closed or Lined channel No Natural features Creates ecological problems. Modifications are failing, needs attention. Flooding occurs.
10	5	1

Channel Stability:

RAT	ING
6	

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

Channel banks are in stable, well protected and vegetated	erosion, sloughing,	Channel banks seriously eroded; stream function impaired, needs
condition.	cracking	immediate attention.
10	5	1

RATING

4

Measure: Channel Stability -BEDS will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

Channel beds a provide deposit	are stable ion and transport	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
	10	5	1

Sediment:

RATING
5

Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
l 10 l	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RA	TING
	3

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid
completely covered	covered with	aquatic vegetation	of any aquatic
with aquatic	aquatic vegetation	in contact with	vegetation
vegetation in contact	in contact with	water during low	
with water during low	water during low	flow conditions	
flow conditions.	flow conditions		
10	7	3	1

Aeration:



Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles	Rocks and riffles in	Channel segment	Channel segment
in streambed >75% of	streambed >33% of	has at least one	is devoid of any
channel length and	channel length or	feature that	turbulence
multiple sources of	multiple sources of	produces	producing features
other turbulence	other turbulence	significant	
producing features	producing features	turbulence during	
	-	low flow conditions	
10	7	3	1

Shade/Temperature Moderation

RATING **6** Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

segment is covered	within channel segment is covered	>25% of water area within channel segment is covered	No shade on water area at any time of day
by shade at midday	by shade at midday	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks	Bare soil on banks, no toe armoring along either bank
		or else sporadic patches of toes armoring	
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
3

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
4

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated invasive cover	25 -75% estimated invasive cover	75-90% estimated invasive cover	>90% estimated invasive cover
	11114401140 001401	11114401140 00101	111740170 00701	
10	7	5	3	1

Aquatic habitat structure

RATING
2

Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

Logs/large woody debris: Fallen trees or parts of trees that provide structure and attachment for
aquatic macroinvertebrates & hiding places for fish.
Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
depth).
Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
over and covers the system surface, providing shade and cover.
Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
underwater pockets used by fish for hiding and protection.
Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
surface forming structure for invertebrate attachment and fish cover.
Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
thick enough to provide invertebrate attachment and fish cover.
Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
current, and relatively shallow depth (usually less than 18 inches).
Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

RATING 1	Measure: Waterways are often important migration corridors for wildlife moving within the watershed. This is particularly true of urban areas where most of the landscape is developed or fragmented. For this characteristic check one selection from each of the three categories below. Use this information to quantitatively assess the functionality of the reach for wildlife travel.							
	☐ Wide (>30 ft on one side) well-connected riparian corridor☐ Narrow (<30 feet on both sides) well-connected riparian corridor							
	 Continuous along entire reach Slightly fragmented by road crossings or passable barriers Substantially fragmented by unvegetated development or impassible barriers 							
Corridor is wide and unbroken. Corridor is slightly fragmented or Corridor is highly fragmented and								
	Diversity of habitat provides good							
cover for	cover for a wide range of animals. protection for animal movement. with little cover for animal							
			movement.					
	10	5	1 1					

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RATING
8

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities



Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5	3	1

Community Served Through Access

RATING
5

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreational	Recreational	Recreational	Recreational	Recreational
facilities are	facilities are	facilities are	facilities are not	facilities are not
accessible to and	accessible to and	accessible to and	easily accessible	easily accessible
serve regional	serve community	serve	but do serve	or do not serve a
interests	interests	neighborhood	limited local	valued public
		interests	interests	interest
10	7	5	3	1

Waterway Name: **69**th **Street Channel** Date: 04/02/2007

Beginning At: Confluence with S. Cedar Creek Ending At: End of Channel

Waterway Scoring Summary

69th Street Channel: Confluence with S. Cedar creek – End of Channel (New)

os Street Channel. Confidence with S. Ce			
Physical Assessment	Score	Possible	% of Total
		Score	Pts
Physical Characteristics	2	10	
Channel Stability - BANKS	6	10	
Channel Stability -BEDS	3	10	
Sediment	3	10	
Physical Subtotal	14	40	35%
Water Quality Assessment			
Absorption and/or Filtration of Pollutants	4	10	
Aeration	2	10	
Shade/Temperature Moderation	2	10	
Channel Bank Integrity and Protection	3	10	
Water Quality Subtotal	11	40	28%
Natural Resource Assessment			
Riparian Width	2	10	
Habitat Diversity	2	10	
Percent Cover of Invasive Plant Species	4	10	
Aquatic Habitat Structure	2	10	Ī
Wildlife Corridor Function	1	10	
Natural Resource Subtotal	11	50	22%
Recreation Facilities Assessment			
Public Access	7	10	
Existing Facilities	4	10	
Community Served Through Access	4	10	
Recreation Facilities Subtotal	15	30	50%
WATERWAY ASSESSMENT TOTAL SCORE	51	160	32%
WATERWAT ASSESSMENT TOTAL SCORE	31	100	J2 /0

Average from previous Assessment: N/A

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)

RATING
2

Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form	Channel has some Natural form	Closed or Lined channel
Channel Type fits Grade, Minor	returning.	No Natural features Creates
or no modifications, capacity		ecological problems.
contained		Modifications are failing, needs
		attention. Flooding occurs.
10	5	1

Channel Stability:

RA	7	ING	
6			

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

Channel banks are in stable, well protected and vegetated	erosion, sloughing,	Channel banks seriously eroded; stream function impaired, needs
condition.	cracking	immediate attention.
10	5	1

RATING

3

Measure: Channel Stability -BEDS will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:

RATING
3

Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
l 10 l	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RATING	
1	

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid	
completely covered	covered with	aquatic vegetation	of any aquatic	l
with aquatic	aquatic vegetation	in contact with	vegetation	
vegetation in contact	in contact with	water during low		
with water during low	water during low	flow conditions		
flow conditions.	flow conditions			
10	7	3	1	l

Aeration:

RATING **2** Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles	Rocks and riffles in	Channel segment	Channel segment
in streambed >75% of	streambed >33% of	has at least one	is devoid of any
channel length and	channel length or	feature that	turbulence
multiple sources of	multiple sources of	produces	producing features
other turbulence	other turbulence	significant	
producing features	producing features	turbulence during	
		low flow conditions	
10	7	3	1

Shade/Temperature Moderation

RATING **2** Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

segment is covered	within channel segment is covered	>25% of water area within channel segment is covered	No shade on water area at any time of day
by shade at midday	by shade at midday	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks or else sporadic patches of toes	Bare soil on banks, no toe armoring along either bank
		patches of toes armoring	
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
2

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
4

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated invasive cover	25 -75% estimated invasive cover	75-90% estimated invasive cover	>90% estimated invasive cover
	11114401140 001401	11114401140 00101	111740170 00701	
10	7	5	3	1

Aquatic habitat structure

RATING
2

Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

	Logs/large woody debris: Fallen trees or parts of trees that provide structure and attachment for aquatic macroinvertebrates & hiding places for fish.
	Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
	deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
	depth).
	Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
	over and covers the system surface, providing shade and cover.
	Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
_	more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
	Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
_	underwater pockets used by fish for hiding and protection.
	Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
	surface forming structure for invertebrate attachment and fish cover.
	Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
	thick enough to provide invertebrate attachment and fish cover.
	Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
_	current, and relatively shallow depth (usually less than 18 inches).
	Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
	side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

RATING 1	Measure: Waterways are often important migration corridors for wildlife moving within the watershed. This is particularly true of urban areas where most of the landscape is developed or fragmented. For this characteristic check one selection from each of the three categories below. Use this information to quantitatively assess the functionality of the reach for wildlife travel.				
		e) well-connected riparian corridor sides) well-connected riparian corri	dor		
	 Continuous along entire reach Slightly fragmented by road crossings or passable barriers Substantially fragmented by unvegetated development or impassible barriers 				
Corridor is wide and unbroken.		Corridor is slightly fragmented or	Corridor is highly fragmented and		
Diversity of habitat provides good		narrow but provides substantial	narrow. It is mostly developed		
cover for a wide range of animals.		protection for animal movement.	with little cover for animal		
movement.					
10		5	1 1		

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RATING
7

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities



Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5	3	1

Community Served Through Access

RA	TING
	4

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreational facilities are accessible to and serve regional interests	Recreational facilities are accessible to and serve community interests	Recreational facilities are accessible to and serve neighborhood interests	Recreational facilities are not easily accessible but do serve limited local interests	Recreational facilities are not easily accessible or do not serve a valued public interest
10	7	5	3	1 1

Waterway Name: Blue Water Ponds (and associated waterways) Date: 04/02/2007

Beginning At: Confluence with the McKenzie Ending At: End of waterways

Waterway Scoring Summary

Blue Water Ponds (and associated waterways): Confluence with McKenzie – End of waterways (New)

Physical Assessment	Score	Possible Score	% of Total Pts
Physical Characteristics	4	10	
Channel Stability - BANKS	5	10	
Channel Stability -BEDS	4	10	
Sediment	6	10	
Physical Subtotal	19	40	48%
Water Quality Assessment			
Absorption and/or Filtration of Pollutants	6	10	
Aeration	4	10	
Shade/Temperature Moderation	4	10	
Channel Bank Integrity and Protection	5	10	
Water Quality Subtotal	19	40	48%
Natural Resource Assessment			
Riparian Width	5	10	
Habitat Diversity	5	10	
Percent Cover of Invasive Plant Species	3	10	
Aquatic Habitat Structure	4	10	
Wildlife Corridor Function	5	10	
Natural Resource Subtotal	22	50	44%
Recreation Facilities Assessment			
Public Access	1	10	
Existing Facilities	1	10	
Community Served Through Access	1	10	
Recreation Facilities Subtotal	3	30	10%
WATERWAY ASSESSMENT TOTAL SCORE	63	160	39%

Average from previous Assessment: N/A

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)



Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form Channel Type fits Grade, Minor or no modifications, capacity contained	Channel has some Natural form returning.	Closed or Lined channel No Natural features Creates ecological problems. Modifications are failing, needs attention. Flooding occurs.
10	5	1

Channel Stability:

RA1	ING
5	

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

Channel banks are in stable, well protected and vegetated condition.	Channel banks show sign of erosion, sloughing, cracking	Channel banks seriously eroded; stream function impaired, needs immediate attention.
10	5	1

RATING

4

Measure: Channel Stability -BEDS will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:

RATING
6

Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
10	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RATING	
6	

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed	>50% of streambed	Isolated patches of	Streambed devoid
completely covered	covered with	aquatic vegetation	of any aquatic
with aquatic	aquatic vegetation	in contact with	vegetation
vegetation in contact	in contact with	water during low	
with water during low	water during low	flow conditions	
flow conditions.	flow conditions		
10	7	3	1

Aeration:



Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles	Rocks and riffles in	Channel segment	Channel segment
in streambed >75% of	streambed >33% of	has at least one	is devoid of any
channel length and	channel length or	feature that	turbulence
multiple sources of	multiple sources of	produces	producing features
other turbulence	other turbulence	significant	
producing features	producing features	turbulence during	
	-	low flow conditions	
10	7	3	1

Shade/Temperature Moderation



Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

segment is covered	within channel segment is covered	>25% of water area within channel segment is covered	No shade on water area at any time of day
by shade at midday	by shade at midday	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks or else sporadic patches of toes	Bare soil on banks, no toe armoring along either bank
		patches of toes armoring	
10	7	3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
5

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not** be counted as an "emergent habitat" as it would not

likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
3

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and outcompeting native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the creek exclusive of the waterway itself.

<10% estimated invasive cover	10-25% estimated	25 -75% estimated	75-90% estimated	>90% estimated invasive cover
	invasive cover	invasive cover	invasive cover	
10	7	5	3	1

Aquatic habitat structure



Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major potential structural components of this habitat type.

Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

	Logs/large woody debris: Fallen trees or parts of trees that provide structure and attachment for aquatic macroinvertebrates & hiding places for fish.
	Deep pools: Areas characterized by a smooth undisturbed surface, generally slow current,
	deep enough to provide protective cover for fish (75 to 100% deeper than the prevailing system
	depth).
	Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation that hangs
	over and covers the system surface, providing shade and cover.
	Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or large slabs
_	more than 10 inches in length. Cobbles are stones between 2.5 and 10 inches in diameter.
	Undercut banks: Eroded areas extending horizontally beneath the surface of the bank forming
_	underwater pockets used by fish for hiding and protection.
	Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath the water
	surface forming structure for invertebrate attachment and fish cover.
	Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic vegetation
	thick enough to provide invertebrate attachment and fish cover.
	Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate or swift
_	current, and relatively shallow depth (usually less than 18 inches).
	Isolated/backwater pools: Areas disconnected from the main channel or connected as a "blind"
	side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

RATING 5	medical transfer and state and state important important confidence for the moving that in the								
	☐ Wide (>30 ft on one side) well-connected riparian corridor☐ Narrow (<30 feet on both sides) well-connected riparian corridor								
		reach ad crossings or passable barriers by unvegetated development or imp	passible barriers						
	 ☐ Forested canopy along majority of the reach ☐ Shrub canopy along majority of the reach ☐ Unmanaged prairie or meadow along majority of reach ☐ Mowed turf or manicured shrub along majority reach. 								
Corridor is wide and unbroken. Diversity of habitat provides good Corridor is slightly fragmented or narrow. It is mostly developed to narrow. It is mostly developed to narrow.									
	a wide range of animals.	protection for animal movement.	with little cover for animal movement.						
	10	5	1						

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RATING
1

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities



Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5	3	1

Community Served Through Access

RATING
1

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreational	Recreational	Recreational	Recreational	Recreational
facilities are	facilities are	facilities are	facilities are not	facilities are not
accessible to and	accessible to and	accessible to and	easily accessible	easily accessible
serve regional	serve community	serve	but do serve	or do not serve a
interests	interests	neighborhood	limited local	valued public
		interests	interests	interest
10	7	5	3	1

Waterway Name: **Cedar Creek** Date: 04/02/2007

Beginning At: Existing Flow Control Gate Ending At: Intake

Waterway Scoring Summary

Cedar Creek: Existing Flow Control Gate – Intake (R1 & R2)

Cedar Creek. Existing Flow Control Gate -	illiane (n	1 0x 11/2)	
Physical Assessment	Score	Possible	% of Total
		Score	Pts
Physical Characteristics	4	10	
Channel Stability - BANKS	4	10	
Channel Stability -BEDS	3	10	
Sediment	5	10	
Physical Subtotal	16	40	40%
Water Quality Assessment			
Absorption and/or Filtration of Pollutants	6	10	
Aeration	2	10	
Shade/Temperature Moderation	5	10	
Channel Bank Integrity and Protection	4	10	
Water Quality Subtotal	17	40	43%
Natural Resource Assessment			
Riparian Width	3	10	
Habitat Diversity	4	10	
Percent Cover of Invasive Plant Species	5	10	
Aquatic Habitat Structure	4	10	
Wildlife Corridor Function	6	10	
Natural Resource Subtotal	22	50	44%
Recreation Facilities Assessment			
Public Access	2	10	
Existing Facilities	1	10	
Community Served Through Access	2	10	
Recreation Facilities Subtotal	5	30	17%
WATERWAY ASSESSMENT TOTAL SCORE	60	160	38%

Average from previous Assessment: 5.7 (Poor)

PHYSICAL CONDITIONS

Channel Physical Characteristics: (Shape / Size)

RATING	ĺ
4	
	I
	l

Measure: Physical Characteristics will be measured against a natural healthy stream with balanced deposition and transport throughout a year. Channel type is a function of the Grade (steep grade straighter stream, flat grade, more sinuosity). Structural modifications should be an enhancement to the stream. While a channel may be an effective means to transport flows, it may be unable to accommodate other goals such as water quality, or habitat resource. Rate the reach for the ability to achieve

multiple goals.

Natural Form	Channel has some Natural form	Closed or Lined channel
Channel Type fits Grade, Minor	returning.	No Natural features Creates
or no modifications, capacity		ecological problems.
contained		Modifications are failing, needs
		attention. Flooding occurs.
10	5	1

Channel Stability:

RA	Τ	ING
	4	ļ

Measure: Channel Stability - BANKS will be measured against a natural healthy stream with functional, stable banks. Vegetated with grasses, native shrubs and trees rate higher than invasive types due to their ability to root deeper and provide more strength. Natural stabilization will weigh higher than artificial methods such as concrete or rip rap lining. *Note bank profile from above.

Channel banks are in stable, well protected and vegetated condition.	Channel banks show sign of erosion, sloughing, cracking	Channel banks seriously eroded; stream function impaired, needs immediate attention.
10	5	1

RATING **3**

Measure: <u>Channel Stability -BEDS</u> will be measured against a natural healthy stream with functional, stable beds. Higher ratings will be given for natural formed beds with balanced deposition and transport. Lower ratings are given for incision, head cutting, or other eroding or flow preventive factors. *Note channel gradient from above.

	Channel bed shows signs of minor failures or erosion. Stream function is not altered	Channel bed seriously eroded and incised; stream function impaired, needs immediate attention.
10	5	1

Sediment:

RATING
5

Measure: Sediment can be an indicator of stability within the channel. Sediment source can be from outside the channel and potentially create stability problems. Rate known sediment values high when there is no indication of damming or starvation within the channel. Rate low when sediment deposition influences flows in a negative manner such as minimal sediment or over deposition creating damming.

Sediment quantities are stable. Provide balanced deposition and transport, creates good environmental conditions		Sediment values seem unbalanced. Stream function seems stable. Sediment problems during specific events.		Sediment volume is either heavy or non-existent. Bed and bank are altered because of extreme sediment conditions. Toxicity is present
l 10 l	7	5	3	1

Water Quality Function

Absorption and/or Filtration of Pollutants:

RA	TING
	6

Measure: One measure of the water quality function of a channel segment is the ability to mitigate for toxics, heavy metals, hydrocarbons, and other suspended pollutants through absorption and filtration by aquatic vegetation. The more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out.

Channel segment is therefore rated on quantity and coverage of aquatic vegetation in streambed.

Streambed completely covered with aquatic vegetation in contact with water during low flow conditions.	>50% of streambed covered with aquatic vegetation in contact with water during low flow conditions	Isolated patches of aquatic vegetation in contact with water during low flow conditions	Streambed devoid of any aquatic vegetation
10 tow corrections.	7	3	1

Aeration:

RATING **2** Measure: Low dissolved oxygen levels (DO) in local streams and flood channels during the summer and fall pose a serious threat to fish populations. DO levels in streams are influenced by many factors, only a few of which are associated with the physical or biological characteristics of the channel itself. One significant measure of the water quality function of a channel segment is whether it provides any source of aeration during low flow conditions. Riffles, splash pools, rock obstructions, drop structures and other features that introduce

even minor turbulence during low flow conditions can help aerate the water and increase the DO levels. Channel segment is therefore rated on the number and type of features that introduce turbulence to stream flows.

Rocks and riffles in streambed >75% of channel length and multiple sources of other turbulence producing features	Rocks and riffles in streambed >33% of channel length or multiple sources of other turbulence producing features	Channel segment has at least one feature that produces significant turbulence during low flow conditions	Channel segment is devoid of any turbulence producing features
10	7	3	1

Shade/Temperature Moderation

RATING **5** Measure: Elevated water temperature is a significant water quality issue for our local waterways, especially in light of forthcoming TMDL temperature requirements for both the Willamette River and Amazon Creek. Stormwater runoff is in and of itself not considered a significant source of temperature pollution. Instead, it is the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The extent and time-of-day of shade over the streambed is the primary measurement of the water quality function of

a stream in terms of temperature moderation. Channel segment is therefore rated on the percent of shade covering the stream flows at midday.

Entire water area within channel segment is covered	within channel	>25% of water area within channel segment is covered	No shade on water area at any time of day
by shade at midday	, •	by shade at midday	
10	7	3	1

Channel Bank Integrity and Protection



Measure: Turbidity resulting from stream bank erosion can be a significant water quality issue. Another measure of water quality function of a channel segment is how susceptible the banks are to the erosive forces of direct rainfall, high peak flows and overall flow volumes. The more rip rap, concrete or other solid material that armors the toe of the channel bank, the less soil is exposed to the erosive effects of rain and stream flows. Additionally, the more willows or other woody vegetation that are rooted at the toe and up the banks of a channel,

the less likelihood there is of toe cutting and bank slumping. In each case, the water quality function is deemed to be higher where the likelihood of erosion and resulting turbidity is mitigated by armoring or woody vegetation. Channel segment is therefore rated on the type and extent of armoring or woody vegetation along the lower stream banks and at the toe of the channel banks.

No bare soil exposed to high flows, armoring or walled banks along both sides of entire channel segment	Woody vegetation along lower banks, rip rap armoring along toe of both banks	Grass slopes between high and low flow zones and either scattered woody vegetation along lower banks or else sporadic patches of toes armoring	Bare soil on banks, no toe armoring along either bank
10	7	armoning 3	1

Natural Resource Functions

Natural resource values are evaluated in this section. The value that a waterway provides to plants and wildlife are emphasized. Several natural resource elements are captured and four specific measures are used to provide a quantitative assessment of the natural resource values embodied in a given reach. The four quantitative assessments include: average riparian width, habitat diversity, percent cover of invasive plant species and aquatic habitat structure. These four components are not meant to be all inclusive of habitat values along a reach, but should serve as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in this assessment include most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway.

Riparian Width

RATING
3

Measure: Average riparian width is used as a measure of terrestrial habitat size. Increasing habitat size relates to increased population sizes and increased biological diversity. Width is averaged along the entire reach and includes both banks of the waterway but is exclusive of the waterway itself.

Average	>90	81-90	71-80	61-70	51-60	41-50	31-40	21-30	11-20	0-10
width	feet	feet	feet	feet	feet	feet	feet	feet	feet	feet
Score	10	9	8	7	6	5	4	3	2	1

Habitat diversity



Measure: A diversity of habitat types will support a broader array of species during a broader array of life stages. The number of different habitat types along a reach is used as a coarse measure of potential biological diversity. One point is given for each substantial habitat type. "Substantial" is a relative term but is meant to indicate that the habitat is serving in a functional capacity for wildlife. For example, a one foot wide linear strip of reed canary grass along the water's edge would **not**

be counted as an "emergent habitat" as it would not likely provide "substantial" habitat value. However, a relatively small vernal pool within a wetland prairie would get a point as this special habitat will provide most of its potential functions despite being small. The following list of habitat types is used to evaluate a reach for a 100 foot width along the reach.

8 or more	5 habitats present	3 habitats present	2 habitats present	No listed habitats
habitats present				present.
10	7	5	3	1

Percent cover of invasive plant species

RATING
5

Measure: Estimated percent cover of invasive plant species is a measure of terrestrial habitat integrity. Invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife species and out-competing native plant species. Cover is estimated for the entire waterway reach for a total width of 100 ft (including one or both sides of the

creek exclusive of the waterway itself.

<10% estimated	10-25%	25 -75%	75-90%	>90% estimated
invasive cover	estimated	estimated	estimated	invasive cover
	invasive cover	invasive cover	invasive cover	
10	7	5	3	1

Aquatic habitat structure



Measure: Aquatic habitat diversity is related directly to the quality of the habitat structure and can serve as a measure of aquatic habitat quality and potential biological diversity. This assessment element measures availability of physical habitat for fish. The potential for the maintenance of a healthy fish community and its ability to recover from disturbance is dependent on the variety and abundance of suitable habitat and cover available. The following list includes many of the major

potential structural components of this habitat type. Evaluate each reach to identify if the component is present or not and score appropriately.

Habitat structure components:

Logs/large woody debris: Fallen trees or parts of trees that provide structure and
attachment for aquatic macroinvertebrates & hiding places for fish.
Deep pools: Areas characterized by a smooth undisturbed surface, generally slow
current, deep enough to provide protective cover for fish (75 to 100% deeper than the
prevailing system depth).
Overhanging vegetation: Trees, shrubs, vines, or perennial herbaceous vegetation
that hangs over and covers the system surface, providing shade and cover.
Boulders/cobble: Boulders are rounded stones more than 10 inches in diameter or
large slabs more than 10 inches in length. Cobbles are stones between 2.5 and 10
inches in diameter.
Undercut banks: Eroded areas extending horizontally beneath the surface of the bank
forming underwater pockets used by fish for hiding and protection.
Thick root mats: Dense mats of roots and rootlets (generally from trees) at or beneath
the water surface forming structure for invertebrate attachment and fish cover.
☐ Dense macrophyte beds: Beds of emergent, floating leaf, or sub-merged aquatic
vegetation thick enough to provide invertebrate attachment and fish cover.
Riffles: Area characterized by broken water surface, rocky or firm substrate, moderate
or swift current, and relatively shallow depth (usually less than 18 inches).
☐ Isolated/backwater pools: Areas disconnected from the main channel or connected as
a "blind" side channel, characterized by a lack of flow except in periods of high water.

>7 cover types available	6 to 7 cover types available	4 to 5 cover types available	2 to 3 cover types available	None to 1 cover type available
10	8	5	3	1

Connectivity

within the watershed. landscape is develope from each of the three	s are often important migration co This is particularly true of urbared or fragmented. For this character e categories below. Use this informer reach for wildlife travel.	areas where most of the teristic check one selection								
<u> </u>	☐ Wide (>30 ft on one side) well-connected riparian corridor☐ Narrow (<30 feet on both sides) well-connected riparian corridor									
Slightly fragmented by	 Continuous along entire reach Slightly fragmented by road crossings or passable barriers Substantially fragmented by unvegetated development or impassible barriers 									
Shrub canopy along m Unmanaged prairie or	ng majority of the reach najority of the reach meadow along majority of reach red shrub along majority reach.									
Corridor is wide and unbroken.	Corridor is slightly fragmented or	Corridor is highly fragmented								
good cover for a wide range of	Diversity of habitat provides narrow but provides substantial and narrow. It is mostly good cover for a wide range of protection for animal movement.									
animals.	protection for admindren movement.	animal movement.								
10	5	1								

Recreation Functions

Recreation values are evaluated in this section. The value that a waterway provides to the community as a recreational resource is important to consider as projects will be better supported by the community if recreational issues are addressed.

Public Access

RA	TING
	2

Measure: This measure quantifies the percentage of the reach that is currently legally accessible to the public through existing easements or ownership. One point is given for each 10% incremental linear area along the waterway that is accessible to the public under current conditions either through ownership or easement. This measure does not account for the existence of paths or other

facilities but only legal access.

100% of reach is	60-70% of reach	40-50% of reach	20-30% of reach	10% or less of
currently	is currently	is currently	is currently	reach is currently
accessible	accessible	accessible	accessible	accessible
10	7	5	3	1

Existing Facilities

RATING
1

Measure: This measure describes the existence of facilities that accommodate recreation. The measure emphasizes trails and parking lots as the primary recreational features quantified.

Free public parking is available and there is access to a paved bike path along the entire reach.	There is access along the entire reach on a paved bike path.	There is access along the entire reach on a dirt, bark or gravel footpath that is maintained as such.	There is access along only part of the reach on an established and maintained path.	There are no facilities along this reach.
10	7	5	3	1

Community Served Through Access

RA	7	ING
	2	2

Measure: This measure attempts to capture the value that recreational facilities provide to the public. Some facilities will be more accessible than others or serve broader recreation goals. The measure quantifies the level of access that is provided to the community.

Recreational facilities are accessible to and serve regional interests	Recreational facilities are accessible to and serve community interests	Recreational facilities are accessible to and serve neighborhood interests	Recreational facilities are not easily accessible but do serve limited local interests	Recreational facilities are not easily accessible or do not serve a valued public interest
10	7	5	3	1

ATTACHMENT 2

Existing & Restored Environmental Benefits Amazon Creek and Cedar Creek Planning Areas

The waterway assessment model was developed collaboratively by a team of natural resource specialists from two local sponsors, the City of Eugene and the City of Springfield, along with assistance from the Lane Council of Governments and the Portland District of the U.S. Army Corps of Engineers. The model is an adaptation of existing waterway assessment tools that the two cities had been using to evaluate the waterway conditions, which enabled a considerable amount of pre-existing data to be utilized. The model was customized specifically for the Metro Waterways Study so that it would better assess outputs related specifically to the study goals and the unique conditions associated with waterways found in the Eugene-Springfield area and the southern Willamette Valley. The Waterway Assessment Model was used to evaluate the existing condition of all waterways and individual reaches within the Amazon Creek and Cedar Creek planning areas based on 2006 and 2007 existing conditions. This enabled the study team to determine which of the waterway segments were in relatively good condition and which waterways were in a degraded condition and would be evaluated for possible restoration under the study. Restoration options were then developed for each of the degraded waterway reaches through an extensive multi-jurisdictional design process. The assessment model was then reapplied to each of the waterway reaches where restoration measures were proposed to measure the change in environmental outputs. This assumed that the restoration options would be fully implemented as proposed. This evaluation allowed the project team to compare and modify the proposed restoration options for the various reaches. The reach options were then combined in various ways to produce varying output levels. This resulted in five alternatives restoration plans for Amazon Creek and four alternatives restoration plans for Cedar Creek. which were then evaluated against the quantitative and qualitative criteria outline in the feasibility report.

The Amazon Creek and Cedar Creek waterway assessments used a combination of field data collected in 2006 and 2007 and other off-site analyses. Each waterway assessment was evaluated under four categories, which included 1) physical conditions, 2) water quality treatment potential, 3) natural resource values, and 4) recreation values. Within each of these categories, specific aspects of channel health were rated on a scale of 1 to 10, with 1 being poor and 10 being excellent. These individual scores were compiled into an overall rating of stream health. Reaches could receive up to 160 points. The final scores, presented as total points as well as percentages, are an indication of the overall health and functionality of that reach. These scores allow pre- and post-enhancement comparison. For the purposes of evaluating restoration benefits against project costs, the recreation category was not included.

Physical Conditions

The first category, physical conditions, evaluated four attributes: physical characteristics; bank channel stability; bed channel stability; and sediment. Physical characteristics included categories for cross section shape, bank profile, channel type, channel gradient, and channel modifications. Bank channel stability was rated on a scale from 1 to 10, the lowest rating being serious erosion, stream functions impaired, in need of immediate work and the highest rating indicating stable, well protected and vegetated conditions. Bed channel stability was rated on a 1 to 10 scale with the lowest rating being serious erosion and incision, impaired stream functions, in need of immediate work. The bank and bed channel stability rating chart also

recorded soil type for each. The evaluation of sediment was based on the 1 to 10 scale with specific notations for sediments sources, sediment size, and known sediment problems.

Water Quality

The second category, water quality, included four attributes: absorption and/or filtration of pollutants; aeration; shade/temperature moderation; and channel bank integrity and protection. The first attribute, pollutant mitigation, rated the channel segment on quantity and coverage of aquatic vegetation in the streambed, based on the fact that the more extensive the coverage of aquatic vegetation in the streambed that is in contact with stream flows during low flow conditions, the greater the amount of pollutants that will possibly be absorbed and/or filtered out. The second attribute, aeration, measured turbulence-creating features such as riffles, splash pools, drop structures, rocks in streambed, weirs or dams, large woody debris, and direct inflow from piped outfall. The third attribute, temperature moderation, measured the extent and time of day of shade over the streambed to account for the extent of solar exposure of the streambed which has the greatest thermal impact to in-stream flows. The third attribute, channel bank integrity and protection, measured bank and toe protection in terms of amount and type of vegetation along toes and banks, and rip-rap along toes and rock or concrete lining of banks.

Natural Resources

The third category, natural resources, considered five attributes: riparian width, habitat diversity, percent cover of invasive plant species, aquatic habitat structure, and wildlife corridor function. The methodology includes the caveat that these attributes were not meant to be all inclusive of habitat values along a reach, but served as a surrogate to approximate important overarching attributes of the natural environment. Other important information captured in the assessment included most common invasive species, most common native species, presence of endangered or rare species or habitats, and migration corridor potential of the waterway. The first attribute, riparian width, was used as a measure of terrestrial habitat size relating to increased population sizes and increased biological diversity. The rating scale used 10 foot increments to measure average width along each reach. The second attribute, habitat diversity, was based on the assumption that a diversity of habitat types will support a broader array of species during a broader array of life stages. Ten different terrestrial and aquatic habitat types were counted, ranging from upland closed canopy forest, various wetland types, to fast and slow water aquatic habitats. The waterways were evaluated for habitats in a 100-foot width along the reaches. The third attribute, invasive plant species, estimated percent cover of invasive plants as a measure of terrestrial habitat integrity, since invasive vegetation reduces the functional habitat value of the riparian area by reducing desirable food, shelter and nesting habitat for native wildlife and outcompeting native plants. Cover was estimated along each reach for a total width of 100 feet exclusive of the creek itself. The fourth attribute, aquatic habitat structure, measured availability of physical habitat for fish. Aquatic habitat diversity is related directly to quality of habitat structure and can serve as a measure of aquatic habitat quality and potential diversity. Specific elements measured included large woody debris, pools, overhanging vegetation, boulders/cobble, undercut banks, thick root mats, dense macrophyte beds, riffles, and isolated backwater pools. The fifth attribute, wildlife corridor function, rated width, degree of physical barriers, and degree/type of vegetation along majority of reach.

The following tables show detailed scores for each of the environmental benefit categories and provides a summary of total scores. Scores were then converted to output units by multiplying the total scores by the acres within each reach. Each Planning Area contains two tables, one where benefits are computed in "points" and the other where benefits are computed "index" units.

			Ce	edar Cr	eek Pla	nning A	rea -	Habitat	Point :	Scores for	Existing	g & Re	estore	ed Con	ditions	(Update	d Feb 20)12)				
	Rea	ach	Physical Condtions (40 points possible)							Water Resources 40 points possibl			Natural Resources (50 points possible)						Total Score		Habitat	
Number	Reach Option	Waterway	Channel Shape	Bank Stability	Bed Stability	Sediment	Total	Pollutant Removal	Aeration	Shade/Water Temperature	Channel Protection	Total	ESA Status	Riparian Width	Habitat Diversity	Percent Invasive Plants	Aquatic Habitat Structure	Wildlife Corridor Function	Total	(130 points possible)	Acres	Output Units
	Existing Conditions		4.0	4.0	3.0	5.0	16.0	6.0	2.0	5.0	4.0	17.0	х	3.0	4.0	5.0	4.0	6.0	22.0	55.0	11.0	605.0
	1A	Cedar Creek	5.0	8.0	5.0	5.0	23.0	6.0	2.0	5.0	9.0	22.0	х	3.0	4.0	5.0	4.0	6.0	22.0	67.0	13.0	871.0
Reach 1	1B	Cedar Creek	5.0	8.0	5.0	5.0	23.0	6.0	2.0	5.0	9.0	22.0	х	3.0	4.0	5.0	4.0	6.0	22.0	67.0	11.0	737.0
	1C	Cedar Creek	9.0	8.0	8.0	8.0	33.0	8.0	6.0	7.0	9.0	30.0	Х	5.0	5.0	7.0	7.0	8.0	32.0	95.0	20.0	1,900.0
	1D	Cedar Creek	5.0	8.0	5.0	5.0	23.0	6.0	2.0	5.0	8.0	21.0	Х	3.0	4.0	5.0	4.0	6.0	22.0	66.0	14.0	924.0
	1E	Cedar Creek	10.0	9.0	10.0	8.0	37.0	8.0	6.0	6.0	10.0	30.0	Х	7.0	5.0	7.0	10.0	8.0	37.0	104.0	20.0	2,080.0
	Existing C	Condtions	4.2	5.8	4.0	4.4	18.4	4.6	3.4	4.2	3.8	16.0		4.6	3.6	4.4	3.4	3.6	17.2	51.6	69.0	3,560.4
		Gray Cr, 75th St Channel, South Cedar Cr, 72nd St Channel, 69th St Channel	4.4	6.2	4.0	4.6	19.2	5.8	3.4	7.8	5.6	22.6	x	6.6	4.2	6.6	4.0	5.2	26.6	68.4	69.0	4,719.6
Reach 2	2B	Gray Cr, 75th St Channel, South Cedar Cr, 72nd St Channel, 69th St Channel	6.4	7.2	5.2	6.4	25.2	7.4	4.6	8.8	7.4	28.2	x	7.6	5.6	7.8	5.4	7.4	33.8	87.2	82.0	7,150.4
	2C	Gray Cr, 75th St Channel, South Cedar Cr, 72nd St Channel, 69th St Channel	6.4	7.2	5.2	6.4	25.2	7.4	4.6	8.8	7.4	28.2	х	7.6	5.6	7.8	5.4	7.4	33.8	87.2	85.0	7,412.0
	Existing C	Conditions	4.0	3.0	4.0	6.0	17.0	6.0	4.0	4.0	5.0	19.0		5.0	5.0	3.0	4.0	5.0	22.0	58.0	48.0	2,784.0
Reach 3	ЗА	Lower Cedar Cr; Blue Water Ponds; Keizer Slough	6.0	7.0	5.0	8.0	26.0	8.0	6.0	8.0	5.0	27.0	х	8.0	6.0	7.0	7.0	8.0	36.0	89.0	48.0	4,272.0
	3B	Lower Cedar Cr; Blue Water Ponds; Keizer Slough	8.0	9.0	6.0	8.0	31.0	10.0	6.0	8.0	5.0	29.0	х	10.0	8.0	9.0	10.0	10.0	47.0	107.0	114.0	12,198.0

	Cedar Creek Planning Area - Habitat Index Scores for Existing & Restored Conditions (Updated Feb 2012)																					
	Rea	ach	Physical Condtions (40 points possible)						Water Resources (40 points possible)				Natural Resources (50 points possible)						Total		Habitat	
Number	Reach Option	Waterway	Channel Shape	Bank Stability	Bed Stability	Sediment	Total	Pollutant Removal	Aeration	Shade - Water Temperature	Channel Protection	Total	ESA Status	Riparian Width	Habitat Diversity	Percent Invasive Plants	Aquatic Habitat Structure	Wildlife Corridor Function	Total	- Enviromental Score (1 Point Possible)	Acres	Habitat Output Units
	Existing Co	onditions	0.40	0.40	0.30	0.50	0.40	0.60	0.20	0.50	0.40	0.43	х	0.30	0.40	0.50	0.40	0.60	0.44	0.42	11.00	4.64
	1A	Cedar Creek	0.50	0.80	0.50	0.50	0.58	0.60	0.20	0.50	0.90	0.55	х	0.30	0.40	0.50	0.40	0.60	0.44	0.52	13.00	6.78
Reach 1	1B	Cedar Creek	0.50	0.80	0.50	0.50	0.58	0.60	0.20	0.50	0.90	0.55	х	0.30	0.40	0.50	0.40	0.60	0.44	0.52	11.00	5.74
	1C	Cedar Creek	0.90	0.80	0.80	0.80	0.83	0.80	0.60	0.70	0.90	0.75	Х	0.50	0.50	0.70	0.70	0.80	0.64	0.74	20.00	14.77
	1D	Cedar Creek	0.50	0.80	0.50	0.50	0.58	0.60	0.20	0.50	0.80	0.53	Х	0.30	0.40	0.50	0.40	0.60	0.44	0.51	14.00	7.19
	1E	Cedar Creek	1.00	0.90	1.00	0.80	0.93	0.80	0.60	0.60	1.00	0.75	Х	0.70	0.50	0.70	1.00	0.80	0.74	0.81	20.00	16.10
	Existing Co	ondtions	0.42	0.58	0.40	0.44	0.46	0.46	0.34	0.42	0.38	0.40		0.46	0.36	0.44	0.34	0.36	0.39	0.42	69.00	28.80
	2A	Gray Cr, 75th St Channel, South Cedar Cr, 72nd St Channel, 69th St Channel	0.44	0.62	0.40	0.46	0.48	0.58	0.34	0.78	0.56	0.57	x	0.66	0.42	0.66	0.40	0.52	0.53	0.53	69.00	36.27
Reach 2	2B	Gray Cr, 75th St Channel, South Cedar Cr, 72nd St Channel, 69th St Channel	0.64	0.72	0.52	0.64	0.63	0.74	0.46	0.88	0.74	0.71	x	0.76	0.56	0.78	0.54	0.74	0.68	0.67	82.00	54.97
	2C	Gray Cr, 75th St Channel, South Cedar Cr, 72nd St Channel, 69th St Channel	0.64	0.72	0.52	0.64	0.63	0.74	0.46	0.88	0.74	0.71	х	0.76	0.56	0.78	0.54	0.74	0.68	0.67	85.00	56.98
	Existing Co	onditions	0.40	0.30	0.40	0.60	0.43	0.60	0.40	0.40	0.50	0.48		0.50	0.50	0.30	0.40	0.50	0.44	0.45	48.00	21.44
Reach 3	ЗА	Lower Cedar Cr; Blue Water Ponds; Keizer Slough	0.60	0.70	0.50	0.80	0.65	0.80	0.60	0.80	0.50	0.68	х	0.80	0.60	0.70	0.70	0.80	0.72	0.68	48.00	32.72
	3В	Lower Cedar Cr; Blue Water Ponds; Keizer Slough	0.80	0.90	0.60	0.80	0.78	1.00	0.60	0.80	0.50	0.73	х	1.00	0.80	0.90	1.00	1.00	0.94	0.81	114.00	92.72

Appendix A HTRW Investigations

This page is intentionally blank

Blue Water Ponds 52nd St & Highbanks Rd Springfield, OR 97478

Inquiry Number: 3791793.5

November 25, 2013

The EDR Aerial Photo Decade Package



EDR Aerial Photo Decade Package

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Thank you for your business.
Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc., All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


Date EDR Searched Historical Sources:

Aerial Photography November 25, 2013

Target Property:

52nd St & Highbanks Rd Springfield, OR 97478

<u>Year</u>	<u>Scale</u>	<u>Details</u>	<u>Source</u>
1947	Aerial Photograph. Scale: 1"=750'	Panel #: 44122-A8, Springfield, OR;/Flight Date: August 31, 1947	EDR
1949	Aerial Photograph. Scale: 1"=750'	Panel #: 44122-A8, Springfield, OR;/Flight Date: October 30, 1949	EDR
1953	Aerial Photograph. Scale: 1"=500'	Panel #: 44122-A8, Springfield, OR;/Flight Date: January 01, 1953	EDR
1965	Aerial Photograph. Scale: 1"=500'	Panel #: 44122-A8, Springfield, OR;/Flight Date: January 01, 1965	EDR
1976	Aerial Photograph. Scale: 1"=1000'	Panel #: 44122-A8, Springfield, OR;/Flight Date: July 01, 1976	EDR
1980	Aerial Photograph. Scale: 1"=1000'	Panel #: 44122-A8, Springfield, OR;/Flight Date: June 30, 1980	EDR
1982	Aerial Photograph. Scale: 1"=500'	Panel #: 44122-A8, Springfield, OR;/Flight Date: September 08, 1982	EDR
1994	Aerial Photograph. Scale: 1"=500'	Panel #: 44122-A8, Springfield, OR;/Flight Date: May 24, 1994	EDR
1994	Aerial Photograph. Scale: 1"=500'	Panel #: 44122-A8, Springfield, OR;/DOQQ - acquisition dates: May 24, 1994	EDR
2005	Aerial Photograph. Scale: 1"=500'	Panel #: 44122-A8, Springfield, OR;/Flight Year: 2005	EDR
2006	Aerial Photograph. Scale: 1"=500'	Panel #: 44122-A8, Springfield, OR;/Flight Year: 2006	EDR
2009	Aerial Photograph. Scale: 1"=500'	Panel #: 44122-A8, Springfield, OR;/Flight Year: 2009	EDR
2011	Aerial Photograph. Scale: 1"=500'	Panel #: 44122-A8, Springfield, OR;/Flight Year: 2011	EDR
2012	Aerial Photograph. Scale: 1"=500'	Panel #: 44122-A8, Springfield, OR;/Flight Year: 2012	EDR






















Blue Water Ponds 52nd St & Highbanks Rd Springfield, OR 97478

Inquiry Number: 3791793.2s

November 21, 2013

The EDR Radius Map™ Report with GeoCheck®




TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	
Map Findings Summary.	4
Map Findings.	7
Orphan Summary	
Government Records Searched/Data Currency Tracking.	GR-1
GEOCHECK ADDENDUM	,
Physical Setting Source Addendum.	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map.	A-5
Physical Setting Source Map.	A-12
Physical Setting Source Map Findings.	A-14
Physical Setting Source Records Searched	A-22

Thank you for your business.Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

52ND ST & HIGHBANKS RD SPRINGFIELD, OR 97478

COORDINATES

Latitude (North): 44.0714000 - 44° 4' 17.04" Longitude (West): 122.9372000 - 122° 56' 13.92"

Universal Tranverse Mercator: Zone 10 UTM X (Meters): 505029.0 UTM Y (Meters): 4879589.0

Elevation: 483 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 44122-A8 SPRINGFIELD, OR

Most Recent Revision: 1986

AERIAL PHOTOGRAPHY IN THIS REPORT

Photo Year: 2012 Source: USDA

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list	
NPL	National Priority List

Proposed NPL..... Proposed National Priority List Sites NPL LIENS..... Federal Superfund Liens Federal Delisted NPL site list Delisted NPL..... National Priority List Deletions Federal CERCLIS list CERCLIS..... FEDERAL FACILITY..... Federal Facility Site Information listing Federal CERCLIS NFRAP site List CERC-NFRAP..... CERCLIS No Further Remedial Action Planned Federal RCRA CORRACTS facilities list CORRACTS..... Corrective Action Report Federal RCRA non-CORRACTS TSD facilities list RCRA-TSDF...... RCRA - Treatment, Storage and Disposal Federal RCRA generators list RCRA-LQG______RCRA - Large Quantity Generators RCRA-SQG...... RCRA - Small Quantity Generators RCRA-CESQG..... RCRA - Conditionally Exempt Small Quantity Generator Federal institutional controls / engineering controls registries US ENG CONTROLS..... Engineering Controls Sites List US INST CONTROL..... Sites with Institutional Controls LUCIS.....Land Use Control Information System Federal ERNS list ERNS..... Emergency Response Notification System State- and tribal - equivalent CERCLIS OR CRL..... Confirmed Release List and Inventory ECSI..... Environmental Cleanup Site Information System State and tribal landfill and/or solid waste disposal site lists SWF/LF..... Solid Waste Facilities List State and tribal leaking storage tank lists Leaking Underground Storage Tank Database INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land State and tribal registered storage tank lists UST..... Underground Storage Tank Database

AST..... Aboveground Storage Tanks

INDIAN UST..... Underground Storage Tanks on Indian Land

FEMA UST..... Underground Storage Tank Listing

State and tribal institutional control / engineering control registries

ENG CONTROLS..... Engineering Controls Recorded at ESCI Sites

INST CONTROL..... Institutional Controls Recorded at ESCI Sites

State and tribal voluntary cleanup sites

INDIAN VCP..... Voluntary Cleanup Priority Listing VCP..... Voluntary Cleanup Program Sites

State and tribal Brownfields sites

BROWNFIELDS..... Brownfields Projects

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

..... Open Dump Inventory

DEBRIS REGION 9..... Torres Martinez Reservation Illegal Dump Site Locations

HIST LF..... Old Closed SW Disposal Sites SWRCY..... Recycling Facility Location Listing

INDIAN ODI...... Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs AOCONCERN......Columbia Slough

CDL...... Uninhabitable Drug Lab Properties

US HIST CDL...... National Clandestine Laboratory Register

Local Land Records

LIENS 2..... CERCLA Lien Information

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System

SPILLS......Spill Database OR HAZMAT..... Hazmat/Incidents

SPILLS 90...... SPILLS 90 data from FirstSearch

Other Ascertainable Records

RCRA NonGen / NLR RCRA - Non Generators DOT OPS..... Incident and Accident Data

DOD...... Department of Defense Sites FUDS..... Formerly Used Defense Sites

CONSENT...... Superfund (CERCLA) Consent Decrees

ROD...... Records Of Decision UMTRA..... Uranium Mill Tailings Sites US MINES..... Mines Master Index File

TRIS...... Toxic Chemical Release Inventory System

TSCA..... Toxic Substances Control Act

Act)/TSCA (Toxic Substances Control Act)

HIST FTTS..... FIFRA/TSCA Tracking System Administrative Case Listing

SSTS..... Section 7 Tracking Systems

ICIS...... Integrated Compliance Information System PADS...... PCB Activity Database System MLTS..... Material Licensing Tracking System RADINFO...... Radiation Information Database

FINDS..... Facility Index System/Facility Registry System RAATS______RCRA Administrative Action Tracking System

RMP..... Risk Management Plans

UIC...... Underground Injection Control Program Database

MANIFEST..... Manifest Information DRYCLEANERS..... Drycleaning Facilities

NPDES...... Wastewater Permits Database AIRS..... Oregon Title V Facility Listing

HSIS..... Hazardous Substance Information Survey

INDIAN RESERV..... Indian Reservations
SCRD DRYCLEANERS..... State Coalition for Remediation of Drycleaners Listing

Potentially Responsible Parties US FIN ASSUR..... Financial Assurance Information 2020 COR ACTION...... 2020 Corrective Action Program List

LEAD SMELTERS..... Lead Smelter Sites EPA WATCH LIST..... EPA WATCH LIST

US AIRS...... Aerometric Information Retrieval System Facility Subsystem

PCB TRANSFORMER...... PCB Transformer Registration Database COAL ASH DOE..... Steam-Electric Plant Operation Data

COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List

COAL ASH..... Coal Ash Disposal Sites Listing

Financial Assurance Information Listing

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP..... EDR Proprietary Manufactured Gas Plants EDR US Hist Auto Stat..... EDR Exclusive Historic Gas Stations EDR US Hist Cleaners...... EDR Exclusive Historic Dry Cleaners

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were not identified.

Unmappable (orphan) sites are not considered in the foregoing analysis.


Due to poor or inadequate address information, the following sites were not mapped. Count: 4 records.

Site Name

SPRINGFIELD AREA GROUNDWATER CONTA SPRINGFIELD AIRPORT (ABANDONED) WOOD STAVE LINE - SPRINGFIELD RAINBOW WATER DISTRICT Database(s)

FINDS, ECSI BROWNFIELDS, ECSI FINDS, VCP, ECSI HSIS


OVERVIEW MAP - 3791793.2s



ADDRESS: 52nd St & Highbanks Rd Springfield OR 97478 44.0714 / 122.9372 INQUIRY #: LAT/LONG:

3791793.2s November 21, 2013 1:15 am DATE:

DETAIL MAP - 3791793.2s



ADDRESS:

LAT/LONG:

52nd St & Highbanks Rd Springfield OR 97478

44.0714 / 122.9372

INQUIRY #: 3791793.2s DATE: November 21, 2013 1:15 am

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMEN	TAL RECORDS							
Federal NPL site list								
NPL Proposed NPL NPL LIENS	1.000 1.000 TP		0 0 NR	0 0 NR	0 0 NR	0 0 NR	NR NR NR	0 0 0
Federal Delisted NPL sit	te list							
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
CERCLIS FEDERAL FACILITY	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
Federal CERCLIS NFRA	P site List							
CERC-NFRAP	0.500		0	0	0	NR	NR	0
Federal RCRA CORRAC	TS facilities li	st						
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-COR	RACTS TSD f	acilities list						
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generator	rs list							
RCRA-LQG RCRA-SQG RCRA-CESQG	0.250 0.250 0.250		0 0 0	0 0 0	NR NR NR	NR NR NR	NR NR NR	0 0 0
Federal institutional cor engineering controls re								
US ENG CONTROLS US INST CONTROL LUCIS	0.500 0.500 0.500		0 0 0	0 0 0	0 0 0	NR NR NR	NR NR NR	0 0 0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equiva	alent CERCLIS	3						
OR CRL ECSI	1.000 1.000		0 0	0 0	0 0	0 0	NR NR	0 0
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking	storage tank l	ists						
LUST INDIAN LUST	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
State and tribal registered storage tank lists								
UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
AST INDIAN UST FEMA UST	0.250 0.250 0.250		0 0 0	0 0 0	NR NR NR	NR NR NR	NR NR NR	0 0 0
State and tribal institution control / engineering con								
ENG CONTROLS INST CONTROL	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
State and tribal voluntary	cleanup sites	5						
INDIAN VCP VCP	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
State and tribal Brownfie	lds sites							
BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMEN	TAL RECORDS							
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / So Waste Disposal Sites	olid							
ODI DEBRIS REGION 9 HIST LF SWRCY INDIAN ODI	0.500 0.500 0.500 0.500 0.500		0 0 0 0	0 0 0 0	0 0 0 0	NR NR NR NR NR	NR NR NR NR NR	0 0 0 0
Local Lists of Hazardous Contaminated Sites	waste /							
US CDL AOCONCERN CDL US HIST CDL	TP 1.000 TP TP		NR 0 NR NR	NR 0 NR NR	NR 0 NR NR	NR 0 NR NR	NR NR NR NR	0 0 0
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency R	elease Report	ts						
HMIRS SPILLS OR HAZMAT SPILLS 90	TP TP TP TP		NR NR NR NR	NR NR NR NR	NR NR NR NR	NR NR NR NR	NR NR NR NR	0 0 0
Other Ascertainable Reco	ords							
RCRA NonGen / NLR DOT OPS DOD FUDS	0.250 TP 1.000 1.000		0 NR 0 0	0 NR 0 0	NR NR 0 0	NR NR 0 0	NR NR NR NR	0 0 0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
CONSENT ROD UMTRA US MINES TRIS TSCA FTTS HIST FTTS SSTS ICIS PADS MLTS RADINFO FINDS RAATS RMP UIC MANIFEST DRYCLEANERS NPDES AIRS HSIS INDIAN RESERV SCRD DRYCLEANERS PRP US FIN ASSUR	1.000 1.000 0.500 0.250 TP	Property	< 1/8 0 0 0 0 0 NR	1/8 - 1/4 0 0 0 0 NR N	1/4 - 1/2 0 0 0 NR NR NR NR NR NR NR NR NR N	1/2 - 1 0 0 R R R R R R R R R R R R R R R R R R	1	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
2020 COR ACTION LEAD SMELTERS EPA WATCH LIST US AIRS PCB TRANSFORMER COAL ASH DOE COAL ASH EPA COAL ASH Financial Assurance EDR HIGH RISK HISTORICA	0.250 TP TP TP TP TP 0.500 0.500 TP		0 NR NR NR NR O O NR	0 NR NR NR NR O O NR	NR NR NR NR NR O O NR	NR NR NR NR NR NR NR	NR NR NR NR NR NR NR NR	0 0 0 0 0 0 0
EDR Exclusive Records EDR MGP EDR US Hist Auto Stat EDR US Hist Cleaners	1.000 0.250 0.250		0 0 0	0 0 0	0 NR NR	0 NR NR	NR NR NR	0 0 0

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Map ID		MAP FINDINGS		
Direction			ı	EDD 10 11 1
Distance				EDR ID Number
Elevation	Site		Database(s)	EPA ID Number

NO SITES FOUND

Count: 4 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
SPRINGFIELD	1007147940	SPRINGFIELD AREA GROUNDWATER CONTA	17S/2W/S30	97477	FINDS, ECSI
SPRINGFIELD	S111254243	RAINBOW WATER DISTRICT	1550 N 42ND ST	97478	HSIS
SPRINGFIELD	S106236342	SPRINGFIELD AIRPORT (ABANDONED)	SW CORNER OF 28TH & OLYMPIC ST	97478	BROWNFIELDS, ECSI
SPRINGFIELD	1006858566	WOOD STAVE LINE - SPRINGFIELD	DOWNTOWN SPRINGFIELD	97477	FINDS, VCP, ECSI

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/26/2013 Source: EPA
Date Data Arrived at EDR: 05/09/2013 Telephone: N/A

Number of Days to Update: 62 Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources

EPA's Environmental Photographic Interpretation Center (EPIC)

Telephone: 202-564-7333

EPA Region 1 EPA Region 6

Telephone 617-918-1143 Telephone: 214-655-6659

EPA Region 3 EPA Region 7

Telephone 215-814-5418 Telephone: 913-551-7247

EPA Region 4 EPA Region 8

Telephone 404-562-8033 Telephone: 303-312-6774

EPA Region 5 EPA Region 9

Telephone 312-886-6686 Telephone: 415-947-4246

EPA Region 10

Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/26/2013 Source: EPA
Date Data Arrived at EDR: 05/09/2013 Telephone: N/A

Number of Days to Update: 62 Next Scheduled EDR Contact: 01/20/2014
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Source: EPA

Date of Government Version: 10/15/1991 Date Data Arrived at EDR: 02/02/1994 Date Made Active in Reports: 03/30/1994

Number of Days to Update: 56

Telephone: 202-564-4267 Last EDR Contact: 08/15/2011

Next Scheduled EDR Contact: 11/28/2011 Data Release Frequency: No Update Planned

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/26/2013 Date Data Arrived at EDR: 05/09/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 62

Source: EPA Telephone: N/A

Last EDR Contact: 11/11/2013

Next Scheduled EDR Contact: 01/20/2014 Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/26/2013 Date Data Arrived at EDR: 05/29/2013 Date Made Active in Reports: 08/09/2013

Number of Days to Update: 72

Source: EPA Telephone: 703-412-9810 Last EDR Contact: 11/11/2013

Next Scheduled EDR Contact: 12/09/2013 Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 07/31/2012 Date Data Arrived at EDR: 10/09/2012 Date Made Active in Reports: 12/20/2012

Number of Days to Update: 72

Source: Environmental Protection Agency

Telephone: 703-603-8704 Last EDR Contact: 10/11/2013

Next Scheduled EDR Contact: 01/20/2014 Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 04/26/2013 Date Data Arrived at EDR: 05/29/2013 Date Made Active in Reports: 08/09/2013

Number of Days to Update: 72

Source: EPA Telephone: 703-412-9810 Last EDR Contact: 11/11/2013

Next Scheduled EDR Contact: 12/09/2013 Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 07/11/2013 Date Data Arrived at EDR: 08/08/2013 Date Made Active in Reports: 09/13/2013

Number of Days to Update: 36

Source: EPA

Telephone: 800-424-9346 Last EDR Contact: 10/02/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 07/11/2013 Date Data Arrived at EDR: 08/08/2013 Date Made Active in Reports: 09/13/2013

Number of Days to Update: 36

Source: Environmental Protection Agency

Telephone: (206) 553-1200 Last EDR Contact: 10/02/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 07/11/2013 Date Data Arrived at EDR: 08/08/2013 Date Made Active in Reports: 09/13/2013

Number of Days to Update: 36

Source: Environmental Protection Agency

Telephone: (206) 553-1200 Last EDR Contact: 10/02/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 07/11/2013 Date Data Arrived at EDR: 08/08/2013 Date Made Active in Reports: 09/13/2013

Number of Days to Update: 36

Source: Environmental Protection Agency

Telephone: (206) 553-1200 Last EDR Contact: 10/02/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 07/11/2013 Date Data Arrived at EDR: 08/08/2013 Date Made Active in Reports: 09/13/2013

Number of Days to Update: 36

Source: Environmental Protection Agency

Telephone: (206) 553-1200 Last EDR Contact: 10/02/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 06/17/2013 Date Data Arrived at EDR: 06/21/2013 Date Made Active in Reports: 10/03/2013 Number of Days to Update: 104 Source: Environmental Protection Agency Telephone: 703-603-0695 Last EDR Contact: 09/10/2013

Next Scheduled EDR Contact: 12/23/2013 Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 06/17/2013 Date Data Arrived at EDR: 06/21/2013 Date Made Active in Reports: 10/03/2013 Source: Environmental Protection Agency Telephone: 703-603-0695 Last EDR Contact: 09/10/2013

Number of Days to Update: 104 Next Scheduled EDR Contact: 12/23/2013
Data Release Frequency: Varies

Data Noicase Frequ

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 08/20/2013 Date Data Arrived at EDR: 08/23/2013 Date Made Active in Reports: 11/01/2013 Source: Department of the Navy Telephone: 843-820-7326 Last EDR Contact: 11/18/2013

Number of Days to Update: 70

Next Scheduled EDR Contact: 03/03/2014 Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 01/17/2013 Date Made Active in Reports: 02/15/2013

Telephone: 202-267-2180 Last EDR Contact: 10/01/2013

Number of Days to Update: 29

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Annually

Source: National Response Center, United States Coast Guard

State- and tribal - equivalent CERCLIS

CRL: Confirmed Release List and Inventory All facilities with a confirmed release.

Date of Government Version: 08/19/2013 Date Data Arrived at EDR: 08/22/2013 Date Made Active in Reports: 11/06/2013

Number of Days to Update: 76

Source: Department of Environmental Quality

Telephone: 503-229-6170 Last EDR Contact: 08/22/2013

Next Scheduled EDR Contact: 12/02/2013 Data Release Frequency: Quarterly

ECSI: Environmental Cleanup Site Information System

Sites that are or may be contaminated and may require cleanup.

Date of Government Version: 10/01/2013 Date Data Arrived at EDR: 10/24/2013 Date Made Active in Reports: 11/06/2013

Number of Days to Update: 13

Source: Department of Environmental Quality

Telephone: 503-229-6629 Last EDR Contact: 10/24/2013

Next Scheduled EDR Contact: 02/03/2014 Data Release Frequency: Quarterly

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Solid Waste Facilities List

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites

Date of Government Version: 08/01/2013
Date Data Arrived at EDR: 08/28/2013
Date Made Active in Reports: 11/04/2013

Number of Days to Update: 68

Source: Department of Environmental Quality

Telephone: 503-229-6299 Last EDR Contact: 08/23/2013

Next Scheduled EDR Contact: 12/09/2013 Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LUST: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 07/01/2013 Date Data Arrived at EDR: 08/22/2013 Date Made Active in Reports: 11/04/2013

Number of Days to Update: 74

Source: Department of Environmental Quality

Telephone: 503-229-5790 Last EDR Contact: 08/22/2013

Next Scheduled EDR Contact: 12/02/2013 Data Release Frequency: Quarterly

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 07/29/2013 Date Data Arrived at EDR: 07/30/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 94

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Quarterly

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 08/27/2012 Date Data Arrived at EDR: 08/28/2012 Date Made Active in Reports: 10/16/2012

Number of Days to Update: 49

Source: EPA Region 8 Telephone: 303-312-6271 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 03/01/2013 Date Data Arrived at EDR: 03/01/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 42

Source: Environmental Protection Agency

Telephone: 415-972-3372 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Quarterly

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 08/20/2013 Date Data Arrived at EDR: 08/23/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 70

Source: EPA, Region 5 Telephone: 312-886-7439 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 02/01/2013 Date Data Arrived at EDR: 05/01/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 184

Source: EPA Region 1 Telephone: 617-918-1313 Last EDR Contact: 11/01/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 08/01/2013 Date Data Arrived at EDR: 08/02/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 91

Source: EPA Region 4 Telephone: 404-562-8677 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Semi-Annually

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 09/12/2011 Date Data Arrived at EDR: 09/13/2011 Date Made Active in Reports: 11/11/2011

Number of Days to Update: 59

Source: EPA Region 6 Telephone: 214-665-6597 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 08/27/2013 Date Data Arrived at EDR: 08/27/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 66

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Varies

State and tribal registered storage tank lists

UST: Underground Storage Tank Database

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 07/01/2013 Date Data Arrived at EDR: 08/22/2013 Date Made Active in Reports: 11/04/2013

Number of Days to Update: 74

Source: Department of Environmental Quality

Telephone: 503-229-5815 Last EDR Contact: 08/22/2013

Next Scheduled EDR Contact: 12/02/2013 Data Release Frequency: Quarterly

AST: Aboveground Storage Tanks

Aboveground storage tank locations reported to the Office of State Fire Marshal.

Date of Government Version: 07/23/2013 Date Data Arrived at EDR: 10/17/2013 Date Made Active in Reports: 11/06/2013

Number of Days to Update: 20

Source: Office of State Fire Marshal Telephone: 503-378-3473 Last EDR Contact: 10/17/2013

Next Scheduled EDR Contact: 02/17/2014 Data Release Frequency: Semi-Annually

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 09/28/2012 Date Data Arrived at EDR: 11/07/2012 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 156

Source: EPA, Region 1 Telephone: 617-918-1313 Last EDR Contact: 11/01/2014

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 08/01/2013 Date Data Arrived at EDR: 08/02/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 91

Source: EPA Region 4 Telephone: 404-562-9424 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 08/20/2013 Date Data Arrived at EDR: 08/23/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 70

Source: EPA Region 5 Telephone: 312-886-6136 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/10/2011 Date Data Arrived at EDR: 05/11/2011 Date Made Active in Reports: 06/14/2011

Number of Days to Update: 34

Source: EPA Region 6 Telephone: 214-665-7591 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Semi-Annually

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 02/28/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 43

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 07/29/2013 Date Data Arrived at EDR: 08/01/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 92

Source: EPA Region 8 Telephone: 303-312-6137 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 02/05/2013 Date Data Arrived at EDR: 02/06/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 65

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 02/21/2013 Date Data Arrived at EDR: 02/26/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 45

Source: EPA Region 9 Telephone: 415-972-3368 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Quarterly

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010 Date Data Arrived at EDR: 02/16/2010 Date Made Active in Reports: 04/12/2010

Number of Days to Update: 55

Source: FEMA

Telephone: 202-646-5797 Last EDR Contact: 10/17/2013

Next Scheduled EDR Contact: 01/27/2014 Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Engineering Controls Recorded at ESCI Sites

Engineering controls are physical measures selected or approved by the Director for the purpose of preventing or minimizing exposure to hazardous substances. Engineering controls may include, but are not limited to, fencing, capping, horizontal or vertical barriers, hydraulic controls, and alternative water supplies.

Date of Government Version: 10/01/2013 Date Data Arrived at EDR: 10/24/2013 Date Made Active in Reports: 11/06/2013

Number of Days to Update: 13

Source: Department of Environmental Quality

Telephone: 503-229-5193 Last EDR Contact: 10/24/2013

Next Scheduled EDR Contact: 02/03/2014 Data Release Frequency: Quarterly

INST CONTROL: Institutional Controls Recorded at ESCI Sites

An institutional control is a legal or administrative tool or action taken to reduce the potential for exposure to hazardous substances. Institutional controls may include, but are not limited to, use restrictions, environmental monitoring requirements, and site access and security measures.

Date of Government Version: 10/01/2013 Date Data Arrived at EDR: 10/24/2013 Date Made Active in Reports: 11/06/2013

Number of Days to Update: 13

Source: Department of Environmental Quality

Telephone: 503-229-5193 Last EDR Contact: 10/24/2013

Next Scheduled EDR Contact: 02/03/2014
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 09/28/2012 Date Data Arrived at EDR: 10/02/2012 Date Made Active in Reports: 10/16/2012

Number of Days to Update: 14

Source: EPA, Region 1 Telephone: 617-918-1102 Last EDR Contact: 10/01/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008 Date Data Arrived at EDR: 04/22/2008 Date Made Active in Reports: 05/19/2008

Number of Days to Update: 27

Source: EPA, Region 7 Telephone: 913-551-7365 Last EDR Contact: 04/20/2009

Next Scheduled EDR Contact: 07/20/2009

Data Release Frequency: Varies

VCS: Voluntary Cleanup Program Sites

Responsible parties have entered into an agreement with DEQ to voluntarily address contamination associated with

their property.

Date of Government Version: 07/22/2013 Date Data Arrived at EDR: 07/26/2013 Date Made Active in Reports: 09/06/2013

Number of Days to Update: 42

Source: DEQ

Telephone: 503-229-5256 Last EDR Contact: 11/07/2013

Next Scheduled EDR Contact: 01/20/2014 Data Release Frequency: Quarterly

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Projects

Brownfields investigations and/or cleanups that have been conducted in Oregon.

Date of Government Version: 08/19/2013 Date Data Arrived at EDR: 08/22/2013 Date Made Active in Reports: 11/06/2013

Number of Days to Update: 76

Source: Department of Environmental Quality

Telephone: 503-229-6801 Last EDR Contact: 08/22/2013

Next Scheduled EDR Contact: 12/02/2013 Data Release Frequency: Semi-Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 06/24/2013 Date Data Arrived at EDR: 06/25/2013 Date Made Active in Reports: 08/09/2013

Number of Days to Update: 45

Source: Environmental Protection Agency

Telephone: 202-566-2777 Last EDR Contact: 09/24/2013

Next Scheduled EDR Contact: 01/08/2014 Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009 Date Data Arrived at EDR: 05/07/2009 Date Made Active in Reports: 09/21/2009

Number of Days to Update: 137

Source: EPA, Region 9 Telephone: 415-947-4219 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985 Date Data Arrived at EDR: 08/09/2004 Date Made Active in Reports: 09/17/2004

Number of Days to Update: 39

Source: Environmental Protection Agency

Telephone: 800-424-9346 Last EDR Contact: 06/09/2004 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

HIST LF: Old Closed SW Disposal Sites

A list of solid waste disposal sites that have been closed for a long while.

Date of Government Version: 04/01/2000 Date Data Arrived at EDR: 07/08/2003 Date Made Active in Reports: 07/18/2003

Number of Days to Update: 10

Source: Department of Environmental Quality

Telephone: 503-229-5409 Last EDR Contact: 07/08/2003 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

SWRCY: Recycling Facility Location Listing A listing of recycling facility locations.

Date of Government Version: 09/03/2013 Date Data Arrived at EDR: 09/05/2013 Date Made Active in Reports: 11/04/2013

Number of Days to Update: 60

Source: Department of Environmental Quality

Telephone: 503-229-5353 Last EDR Contact: 09/05/2013

Next Scheduled EDR Contact: 12/16/2013 Data Release Frequency: Quarterly

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998 Date Data Arrived at EDR: 12/03/2007 Date Made Active in Reports: 01/24/2008

Number of Days to Update: 52

Source: Environmental Protection Agency

Telephone: 703-308-8245 Last EDR Contact: 11/04/2013

Next Scheduled EDR Contact: 02/17/2014 Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 08/06/2013 Date Data Arrived at EDR: 09/11/2013 Date Made Active in Reports: 10/03/2013

Number of Days to Update: 22

Source: Drug Enforcement Administration

Telephone: 202-307-1000 Last EDR Contact: 09/04/2013

Next Scheduled EDR Contact: 12/16/2013 Data Release Frequency: Quarterly

AOC COL: Columbia Slough

Columbia Slough waterway boundaries.

Date of Government Version: 08/10/2005 Date Data Arrived at EDR: 05/17/2006 Date Made Active in Reports: 06/16/2006

Number of Days to Update: 30

Source: City of Portland Environmental Services

Telephone: 503-823-5310 Last EDR Contact: 03/13/2007 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

AOC MU: East Multnomah County Area

Approximate extent of TSA VOC plume February, 2002

Date of Government Version: N/A
Date Data Arrived at EDR: 10/07/2002
Date Made Active in Reports: 10/22/2002

Number of Days to Update: 15

Source: City of Portland Environmental Services

Telephone: 503-823-5310 Last EDR Contact: 03/13/2007 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

CDL 2: Clandestine Drug Lab Site Listing

A listing of clandestine drug lab site locations included in the Incident database.

Date of Government Version: 08/01/2012 Date Data Arrived at EDR: 08/03/2012 Date Made Active in Reports: 09/11/2012

Number of Days to Update: 39

Source: Oregon State Police Telephone: 503-373-1540 Last EDR Contact: 11/08/2013

Next Scheduled EDR Contact: 02/17/2014

Data Release Frequency: Varies

CDL: Uninhabitable Drug Lab Properties

The properties listed on these county pages have been declared by a law enforcement agency to be unfit for use due to meth lab and/or storage activities. The properties are considered uninhabitable until cleaned up by a state certified decontamination contractor and a certificate of fitness is issued by the Oregon Health Division.

Date of Government Version: 07/22/2013 Date Data Arrived at EDR: 08/15/2013 Date Made Active in Reports: 09/03/2013

Number of Days to Update: 19

Source: Department of Consumer & Business Services

Telephone: 503-378-4133 Last EDR Contact: 11/11/2013

Next Scheduled EDR Contact: 02/24/2014

Data Release Frequency: Varies

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007 Date Data Arrived at EDR: 11/19/2008 Date Made Active in Reports: 03/30/2009

Number of Days to Update: 131

Source: Drug Enforcement Administration

Telephone: 202-307-1000 Last EDR Contact: 03/23/2009

Next Scheduled EDR Contact: 06/22/2009 Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/06/2013 Date Data Arrived at EDR: 04/25/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 15

Source: Environmental Protection Agency

Telephone: 202-564-6023 Last EDR Contact: 11/13/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 01/03/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 55

Source: U.S. Department of Transportation

Telephone: 202-366-4555 Last EDR Contact: 10/01/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Annually

SPILLS: Spill Data

Oil and hazardous material spills reported to the Environmental Response Program.

Date of Government Version: 10/01/2013 Date Data Arrived at EDR: 10/16/2013 Date Made Active in Reports: 11/04/2013

Number of Days to Update: 19

Source: Department of Environmental Quality

Telephone: 503-229-5815 Last EDR Contact: 10/07/2013

Next Scheduled EDR Contact: 01/20/2014 Data Release Frequency: Semi-Annually

HAZMAT: Hazmat/Incidents

Hazardous material incidents reported to the State Fire Marshal by emergency responders. The hazardous material may or may not have been released.

Date of Government Version: 07/16/2013 Date Data Arrived at EDR: 08/07/2013 Date Made Active in Reports: 09/03/2013

Number of Days to Update: 27

Source: State Fire Marshal's Office Telephone: 503-373-1540 Last EDR Contact: 11/08/2013

Next Scheduled EDR Contact: 02/17/2014 Data Release Frequency: Semi-Annually

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 05/01/2006 Date Data Arrived at EDR: 01/03/2013 Date Made Active in Reports: 02/22/2013

Number of Days to Update: 50

Source: FirstSearch Telephone: N/A

Last EDR Contact: 01/03/2013 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 07/11/2013 Date Data Arrived at EDR: 08/08/2013 Date Made Active in Reports: 09/13/2013

Number of Days to Update: 36

Source: Environmental Protection Agency

Telephone: (206) 553-1200 Last EDR Contact: 10/02/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012 Date Data Arrived at EDR: 08/07/2012 Date Made Active in Reports: 09/18/2012

Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety

Telephone: 202-366-4595 Last EDR Contact: 11/06/2013

Next Scheduled EDR Contact: 02/17/2014 Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 11/10/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 62

Source: USGS

Telephone: 888-275-8747 Last EDR Contact: 10/18/2013

Next Scheduled EDR Contact: 01/27/2014 Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 02/26/2013 Date Made Active in Reports: 03/13/2013

Number of Days to Update: 15

Source: U.S. Army Corps of Engineers

Telephone: 202-528-4285 Last EDR Contact: 09/10/2013

Next Scheduled EDR Contact: 12/23/2013

Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 06/30/2013 Date Data Arrived at EDR: 08/07/2013 Date Made Active in Reports: 10/03/2013

Number of Days to Update: 57

Source: Department of Justice, Consent Decree Library

Telephone: Varies

Last EDR Contact: 09/30/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 04/26/2013 Date Data Arrived at EDR: 06/11/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 143

Source: EPA

Telephone: 703-416-0223 Last EDR Contact: 09/13/2013

Next Scheduled EDR Contact: 12/23/2013 Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010 Date Data Arrived at EDR: 10/07/2011 Date Made Active in Reports: 03/01/2012

Number of Days to Update: 146

Source: Department of Energy Telephone: 505-845-0011 Last EDR Contact: 05/28/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Varies

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/01/2013 Date Data Arrived at EDR: 09/05/2013 Date Made Active in Reports: 10/03/2013

Number of Days to Update: 28

Source: Department of Labor, Mine Safety and Health Administration

Telephone: 303-231-5959 Last EDR Contact: 09/05/2013

Next Scheduled EDR Contact: 12/16/2013 Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 07/31/2013 Date Made Active in Reports: 09/13/2013

Number of Days to Update: 44

Source: EPA

Telephone: 202-566-0250 Last EDR Contact: 08/30/2013

Next Scheduled EDR Contact: 12/09/2013 Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2006 Date Data Arrived at EDR: 09/29/2010 Date Made Active in Reports: 12/02/2010

Number of Days to Update: 64

Source: EPA

Telephone: 202-260-5521 Last EDR Contact: 09/24/2013

Next Scheduled EDR Contact: 01/08/2014 Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances

Telephone: 202-566-1667 Last EDR Contact: 08/22/2013

Next Scheduled EDR Contact: 12/09/2013 Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA

Telephone: 202-566-1667 Last EDR Contact: 08/22/2013

Next Scheduled EDR Contact: 12/09/2013
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006 Date Data Arrived at EDR: 03/01/2007 Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2007

Next Scheduled EDR Contact: 03/17/2008 Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2008

Next Scheduled EDR Contact: 03/17/2008 Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009 Date Data Arrived at EDR: 12/10/2010 Date Made Active in Reports: 02/25/2011

Number of Days to Update: 77

Source: EPA

Telephone: 202-564-4203 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 07/20/2011 Date Data Arrived at EDR: 11/10/2011 Date Made Active in Reports: 01/10/2012

Number of Days to Update: 61

Source: Environmental Protection Agency

Telephone: 202-564-5088 Last EDR Contact: 10/09/2014

Next Scheduled EDR Contact: 01/27/2014 Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 06/01/2013 Date Data Arrived at EDR: 07/17/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 107

Source: EPA

Telephone: 202-566-0500 Last EDR Contact: 10/18/2013

Next Scheduled EDR Contact: 01/27/2014
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/22/2013 Date Data Arrived at EDR: 08/02/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 91

Source: Nuclear Regulatory Commission

Telephone: 301-415-7169 Last EDR Contact: 09/10/2013

Next Scheduled EDR Contact: 12/23/2013 Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 09/30/2013 Date Data Arrived at EDR: 10/09/2013 Date Made Active in Reports: 11/01/2013

Number of Days to Update: 23

Source: Environmental Protection Agency

Telephone: 202-343-9775 Last EDR Contact: 10/09/2013

Next Scheduled EDR Contact: 01/20/2014 Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 03/08/2013
Date Data Arrived at EDR: 03/21/2013
Date Made Active in Reports: 07/10/2013

Number of Days to Update: 111

Source: EPA

Telephone: (206) 553-1200 Last EDR Contact: 09/11/2013

Next Scheduled EDR Contact: 12/23/2013 Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995 Date Data Arrived at EDR: 07/03/1995 Date Made Active in Reports: 08/07/1995

Number of Days to Update: 35

Source: EPA

Telephone: 202-564-4104 Last EDR Contact: 06/02/2008

Next Scheduled EDR Contact: 09/01/2008 Data Release Frequency: No Update Planned

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 05/08/2012 Date Data Arrived at EDR: 05/25/2012 Date Made Active in Reports: 07/10/2012

Number of Days to Update: 46

Source: Environmental Protection Agency

Telephone: 202-564-8600 Last EDR Contact: 10/28/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 02/26/2013 Date Made Active in Reports: 04/19/2013

Number of Days to Update: 52

Source: EPA/NTIS Telephone: 800-424-9346 Last EDR Contact: 08/26/2013

Next Scheduled EDR Contact: 12/09/2013 Data Release Frequency: Biennially

UIC: Underground Injection Control Program Database

DEQ's Underground Injection Control Program is authorized by the Environmental Protection Agency (EPA) to regulate all underground injection in Oregon to protect groundwater resources.

Date of Government Version: 09/05/2013 Date Data Arrived at EDR: 09/06/2013 Date Made Active in Reports: 11/04/2013

Number of Days to Update: 59

Source: Department of Environmental Quality

Telephone: 503-229-5945 Last EDR Contact: 09/30/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Varies

OR MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 11/30/2012 Date Made Active in Reports: 01/08/2013

Number of Days to Update: 39

Source: Department of Environmental Quality

Telephone: N/A

Last EDR Contact: 11/08/2013

Next Scheduled EDR Contact: 02/24/2014 Data Release Frequency: Annually

DRYCLEANERS: Drycleaning Facilities

A listing of registered drycleaning facilities in Oregon.

Date of Government Version: 08/02/2013 Date Data Arrived at EDR: 08/07/2013 Date Made Active in Reports: 09/03/2013

Number of Days to Update: 27

Source: Department of Environmental Quality

Telephone: 503-229-6783 Last EDR Contact: 11/04/2013

Next Scheduled EDR Contact: 02/17/2014 Data Release Frequency: Varies

NPDES: Wastewater Permits Database

A listing of permitted wastewater facilities.

Date of Government Version: 04/18/2013 Date Data Arrived at EDR: 04/18/2013 Date Made Active in Reports: 05/21/2013

Number of Days to Update: 33

Source: Department of Environmental Quality

Telephone: 503-229-5657 Last EDR Contact: 11/11/2013

Next Scheduled EDR Contact: 02/24/2014 Data Release Frequency: Quarterly

AIRS: Oregon Title V Facility Listing

A listing of Title V facility source and emissions information.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 03/08/2013 Date Made Active in Reports: 04/09/2013

Number of Days to Update: 32

Source: Department of Environmental Quality

Telephone: 503-229-6459 Last EDR Contact: 09/03/2013

Next Scheduled EDR Contact: 12/16/2013 Data Release Frequency: Varies

HSIS: Hazardous Substance Information Survey

Companies in Oregon submitting the Hazardous Substance Information Survey and either reporting or not reporting hazardous substances.

Date of Government Version: 07/23/2013 Date Data Arrived at EDR: 10/17/2013 Date Made Active in Reports: 11/06/2013

Number of Days to Update: 20

Source: State Fire Marshal's Office Telephone: 503-373-1540 Last EDR Contact: 10/17/2013

Next Scheduled EDR Contact: 02/17/2014 Data Release Frequency: Semi-Annually

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater

than 640 acres.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 12/08/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 34

Source: USGS

Telephone: 202-208-3710 Last EDR Contact: 10/18/2013

Next Scheduled EDR Contact: 01/27/2014 Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011 Date Data Arrived at EDR: 03/09/2011 Date Made Active in Reports: 05/02/2011

Number of Days to Update: 54

Source: Environmental Protection Agency

Telephone: 615-532-8599 Last EDR Contact: 11/18/2013

Next Scheduled EDR Contact: 02/03/2014 Data Release Frequency: Varies

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 06/30/2013 Date Data Arrived at EDR: 08/13/2013 Date Made Active in Reports: 09/13/2013

Number of Days to Update: 31

Source: Environmental Protection Agency

Telephone: 617-520-3000 Last EDR Contact: 11/15/2013

Next Scheduled EDR Contact: 02/24/2014 Data Release Frequency: Quarterly

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/04/2013 Date Data Arrived at EDR: 03/15/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 56

Source: Environmental Protection Agency

Telephone: 202-566-1917 Last EDR Contact: 11/18/2013

Next Scheduled EDR Contact: 03/03/2014 Data Release Frequency: Quarterly

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 02/06/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 339

Source: U.S. Geological Survey Telephone: 888-275-8747 Last EDR Contact: 10/18/2013

Next Scheduled EDR Contact: 01/27/2014

Data Release Frequency: N/A

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011 Date Data Arrived at EDR: 10/19/2011 Date Made Active in Reports: 01/10/2012

Number of Days to Update: 83

Source: Environmental Protection Agency

Telephone: 202-566-0517 Last EDR Contact: 11/01/2013

Next Scheduled EDR Contact: 02/11/2014 Data Release Frequency: Varies

COAL ASH DOE: Sleam-Electric Plan Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 08/07/2009 Date Made Active in Reports: 10/22/2009

Number of Days to Update: 76

Source: Department of Energy Telephone: 202-586-8719 Last EDR Contact: 10/15/2013

Next Scheduled EDR Contact: 01/27/2014 Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing

Financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 08/01/2013 Date Data Arrived at EDR: 08/28/2013 Date Made Active in Reports: 11/04/2013

Number of Days to Update: 68

Source: Department of Environmental Quality

Telephone: 503-229-5521 Last EDR Contact: 08/23/2013

Next Scheduled EDR Contact: 12/09/2013

Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 08/17/2010 Date Data Arrived at EDR: 01/03/2011 Date Made Active in Reports: 03/21/2011

Number of Days to Update: 77

Source: Environmental Protection Agency

Telephone: N/A

Last EDR Contact: 09/13/2013

Next Scheduled EDR Contact: 12/23/2013 Data Release Frequency: Varies

COAL ASH: Coal Ash Disposal Sites Listing A listing of coal ash disposal sites.

Date of Government Version: 06/01/2011 Date Data Arrived at EDR: 06/02/2011 Date Made Active in Reports: 06/30/2011

Number of Days to Update: 28

Source: Department of Environmental Quality

Telephone: 541-298-7255 Last EDR Contact: 09/10/2013

Next Scheduled EDR Contact: 12/23/2013 Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information for hazardous waste facilities.

Date of Government Version: 09/06/2013 Date Data Arrived at EDR: 09/11/2013 Date Made Active in Reports: 11/04/2013

Number of Days to Update: 54

Source: Department of Environmental Quality

Telephone: 541-633-2011 Last EDR Contact: 08/23/2013

Next Scheduled EDR Contact: 12/09/2013 Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/29/2013 Date Data Arrived at EDR: 02/14/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 13

Source: Environmental Protection Agency

Telephone: 703-603-8787 Last EDR Contact: 09/24/2013

Next Scheduled EDR Contact: 01/20/2014

Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001 Date Data Arrived at EDR: 10/27/2010 Date Made Active in Reports: 12/02/2010

Number of Days to Update: 36

Source: American Journal of Public Health

Telephone: 703-305-6451 Last EDR Contact: 12/02/2009 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 11/11/2011 Date Data Arrived at EDR: 05/18/2012 Date Made Active in Reports: 05/25/2012

Number of Days to Update: 7

Source: Environmental Protection Agency

Telephone: 703-308-4044 Last EDR Contact: 11/15/2013

Next Scheduled EDR Contact: 02/24/2014 Data Release Frequency: Varies

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 04/15/2013 Date Data Arrived at EDR: 07/03/2013 Date Made Active in Reports: 09/13/2013

Number of Days to Update: 72

Source: EPA

Telephone: 202-564-6023 Last EDR Contact: 10/04/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Quarterly

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 01/23/2013 Date Data Arrived at EDR: 01/30/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 100

Source: EPA

Telephone: 202-564-5962 Last EDR Contact: 09/30/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data A listing of minor source facilities.

Date of Government Version: 01/23/2013 Date Data Arrived at EDR: 01/30/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 100

Source: EPA

Telephone: 202-564-5962 Last EDR Contact: 09/30/2013

Next Scheduled EDR Contact: 01/13/2014 Data Release Frequency: Annually

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Data Release Frequency: No Update Planned

Date of Government Version: N/A Source: EDR, Inc.
Date Data Arrived at EDR: N/A Telephone: N/A
Date Made Active in Reports: N/A Last EDR Contact: N/A

EDR US Hist Auto Stat: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A Source: EDR, Inc.
Date Data Arrived at EDR: N/A Telephone: N/A
Date Made Active in Reports: N/A Last EDR Contact: N/A

Number of Days to Update: N/A Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A Source: EDR, Inc.
Date Data Arrived at EDR: N/A Telephone: N/A
Date Made Active in Reports: N/A Last EDR Contact: N/A

Number of Days to Update: N/A Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Proprietary Historic Dry Cleaners - Cole

Date of Government Version: N/A

Date Data Arrived at EDR: N/A

Date Made Active in Reports: N/A

Last EDR Contact: N/A

Number of Days to Update: N/A Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

EDR US Hist Auto Stat: EDR Proprietary Historic Gas Stations - Cole

Date of Government Version: N/A

Date Data Arrived at EDR: N/A

Date Made Active in Reports: N/A

Last EDR Contact: N/A

Number of Days to Update: N/A

Next Scheduled EDR Contact: N/A

Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD

Telephone: N/A

Date of Government Version: 11/01/2013 Date Data Arrived at EDR: 11/07/2013 Date Made Active in Reports: 11/18/2013

Number of Days to Update: 11

Source: Department of Environmental Conservation

Telephone: 518-402-8651 Last EDR Contact: 11/07/2013

Next Scheduled EDR Contact: 02/17/2014 Data Release Frequency: Annually

Source: Department of Natural Resources

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 08/09/2013 Date Made Active in Reports: 09/27/2013

Number of Days to Update: 49

Last EDR Contact: 09/16/2013

Next Scheduled EDR Contact: 12/30/2013 Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data

Source: Rextag Strategies Corp. Telephone: (281) 769-2247

U.S. Electric Transmission and Power Plants Systems Digital GIS Data

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services,

a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary

and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are

comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Child Care Listings Source: Employment Department Telephone: 503-947-1420

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetlands Inventory Data Source: Oregon Geospatial Enterprise Office

Telephone: 503-378-2166

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image

is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK®-PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

BLUE WATER PONDS 52ND ST & HIGHBANKS RD SPRINGFIELD, OR 97478

TARGET PROPERTY COORDINATES

Latitude (North): 44.0714 - 44° 4' 17.04" Longitude (West): 122.9372 - 122° 56' 13.92"

Universal Tranverse Mercator: Zone 10 UTM X (Meters): 505029.0 UTM Y (Meters): 4879589.0

Elevation: 483 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map: 44122-A8 SPRINGFIELD, OR

Most Recent Revision: 1986

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

- 1. Groundwater flow direction, and
- 2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION


Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General South

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES





Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

FEMA Flood Electronic Data

Target Property County LANE, OR

YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property:

41039C - FEMA DFIRM Flood data

Additional Panels in search area:

Not Reported

NATIONAL WETLAND INVENTORY

NWI Electronic

NWI Quad at Target Property

Data Coverage

SPRINGFIELD

YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID Not Reported LOCATION FROM TP

GENERAL DIRECTION GROUNDWATER FLOW

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

GEOLOGIC AGE IDENTIFICATION


Era: Cenozoic Category: Stratifed Sequence

System: Quaternary Series: Quaternary

Code: Q (decoded above as Era, System & Series)

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 3791793.2s



SITE NAME: Blue Water Ponds
ADDRESS: 52nd St & Highbanks Rd
Springfield OR 97478
LAT/LONG: 44.0714 / 122.9372

CLIENT: US Army Corps of Engineers CONTACT: Alison Burcham

INQUIRY#: 3791793.2s

DATE: November 21, 2013 1:16 am

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Riverwash

Soil Surface Texture: stratified gravel to sand

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high

water table, or are shallow to an impervious layer.

Soil Drainage Class: Poorly drained

Hydric Status: All hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 31 inches

	Soil Layer Information						
Boundary Classification Saturated hydraulic							
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		Soil Reaction (pH)
1	0 inches	59 inches	stratified gravel to sand	Not reported	Not reported	Max: Min:	Max: Min:

Soil Map ID: 2

Soil Component Name: Water

Soil Surface Texture: stratified gravel to sand

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high

water table, or are shallow to an impervious layer.

Soil Drainage Class: Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 3

Soil Component Name: Fluvents

Soil Surface Texture: stratified gravel to sand

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high

water table, or are shallow to an impervious layer.

Soil Drainage Class: Poorly drained

Hydric Status: All hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 4

Soil Component Name: Dixonville

Soil Surface Texture: silty clay loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high

water table, or are shallow to an impervious layer.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 46 inches

Soil Layer Information							
	Воц	undary		Classification		Saturated hydraulic	
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	hydraulic conductivity micro m/sec	
1	0 inches	14 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14 Min: 4	Max: 6.5 Min: 5.6

	Soil Layer Information							
Boundary				(lassification		Saturated hydraulic		
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	conductivity micro m/sec		
2	14 inches	25 inches	silty clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit 50% or more), Fat Clay.	Max: 1.4 Min: 0.42	Max: 6.5 Min: 5.6	
3	25 inches	35 inches	weathered bedrock	Not reported	Not reported	Max: Min:	Max: Min:	

Soil Map ID: 5

Soil Component Name: Dixonville

Soil Surface Texture: silty clay loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high

water table, or are shallow to an impervious layer.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 46 inches

	Soil Layer Information							
	Вои	ındary		Classi	fication	Saturated hydraulic		
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	conductivity micro m/sec	Soil Reaction (pH)	
1	0 inches	14 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14 Min: 4	Max: 6.5 Min: 5.6	
2	14 inches	25 inches	silty clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit 50% or more), Fat Clay.	Max: 1.4 Min: 0.42	Max: 6.5 Min: 5.6	

	Soil Layer Information						
Houndary (Classification				Saturated hydraulic			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		Soil Reaction (pH)
3	25 inches	35 inches	weathered bedrock	Not reported	Not reported	Max: Min:	Max: Min:

Soil Map ID: 6

Soil Component Name: Newberg

Soil Surface Texture: fine sandy loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep,

moderately well and well drained soils with moderately coarse

textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

	Soil Layer Information							
	Bou	ındary		Classi	fication	Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)	
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil			
1	0 inches	14 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 42 Min: 14	Max: 6.5 Min: 5.6	
2	14 inches	64 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 42 Min: 14	Max: 6.5 Min: 5.6	

Soil Map ID: 7

Soil Component Name: Panther

Soil Surface Texture: silty clay loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high

water table, or are shallow to an impervious layer.

Soil Drainage Class: Poorly drained

Hydric Status: All hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 15 inches

	Soil Layer Information							
	Воц	ındary		Classification		Saturated hydraulic		
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	conductivity micro m/sec		
1	0 inches	9 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 4 Min: 1.4	Max: 6.5 Min: 5.6	
2	9 inches	42 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit 50% or more), Fat Clay.	Max: 0.42 Min: 0.01	Max: 6.5 Min: 3.5	
3	42 inches	51 inches	weathered bedrock	Not reported	Not reported	Max: Min:	Max: Min:	

Soil Map ID: 8

Soil Component Name: Philomath

Soil Surface Texture: cobbly silty clay

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high

water table, or are shallow to an impervious layer.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

			3011 Layer	Information			
	Воц	ındary		Classi	fication	Saturated hydraulic	
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	conductivity micro m/sec	Soil Reaction (pH)
1	0 inches	5 inches	cobbly silty clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit 50% or more), Fat Clay.	Max: 14 Min: 4	Max: 6.5 Min: 5.6
2	5 inches	14 inches	cobbly silty clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit 50% or more), Fat Clay.	Max: 1.4 Min: 0.42	Max: 7.3 Min: 5.6
3	14 inches	24 inches	weathered bedrock	Not reported	Not reported	Max: Min:	Max: Min:

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE SEARCH DISTANCE (miles)

Federal USGS 1.000

Federal FRDS PWS Nearest PWS within 1 mile

State Database 1.000

FEDERAL USGS WELL INFORMATION

MAP ID WELL ID FROM TP

No Wells Found

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID WELL ID LOCATION FROM TP


No PWS System Found

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1 A2	ORW400000002013 ORI40000003992	1/2 - 1 Mile East 1/2 - 1 Mile East
A3	ORI40000003992 ORI40000003991	1/2 - 1 Mile East
A4	ORI40000003989	1/2 - 1 Mile East
A5	ORI40000003990	1/2 - 1 Mile East

PHYSICAL SETTING SOURCE MAP - 3791793.2s



SITE NAME: Blue Water Ponds ADDRESS: 52nd St & Highbanks Rd Springfield OR 97478 LAT/LONG: 44.0714 / 122.9372 CLIENT: US Army Corps of Engineers CONTACT: Alison Burcham

INQUIRY #: 3791793.2s

DATE: November 21, 2013 1:16 am

Map ID Direction				
Distance Elevation			Database	EDR ID Number
1 East 1/2 - 1 Mile Higher			OR WELLS	ORW40000002013
Logid: Establby: Horizerr: Sourceowrd: Welltag:	LANE 10591 KARL WOZNIAK 9999 WILLGW 0	Lstupdate: Xysource: Sourceorg:	Not Reported UNKNOWN USGS	
Sownum: Recwell: Lsdelev:	0 9 490	Obswell: Obsflagall: Site id:	9 Not Reported ORW400000002013	}
A2 East 1/2 - 1 Mile Higher			OR WELLS	ORI40000003992
Well inspe:	36345			
Physical I:	Not Reported	Inspection:	07/12/2004	
Startcard :	Not Reported	WI county:	Not Reported	
WI nbr:	Not Reported	Startcard1:	Not Reported	
Well tag n:	Not Reported	No log:	0	
Property o:	Not Reported	Inspecti 1:	Not Reported	
Special st:	0	Title:	Not Reported	
Inspecti 2:	Not Reported	Witnesses:	Not Reported	
Name owner:	BRAINARD, WARREN	With C33C3.	Not Reported	
Street:	Not Reported	City:	Not Reported	
State:	•		Not Reported	
Phone home:	Not Reported	Zip:	•	
	Not Reported 0	Phone comp:	Not Reported	
Gps on wel:	-	Distance t:	Not Reported	
Bearing to:	Not Reported	Drilling m:	Not Reported	
Use of wel:	Not Reported 0	Drilling 1:	0 Not Deported	
Rough log:	-	Inspected :	Not Reported	
Well tag r:	Not Reported	Manitari da	2	
Monitoring:	Not Reported	Monitori 1:	0	
Protective:	0	Well locke:	0	
Consultant:	O Nat Barranta d	Water in v:	0	
Seal test :	Not Reported	Samples ta:	0 Nat Danastad	
Casing dia:	Not Reported	Csg above :	Not Reported	
Csg gauge:	Not Reported	Borehole d:	Not Reported	
Dedicated :	0	Access por:	0	
Access p 1:	Not Reported	Measuring :	Not Reported	
Measuring1:	0 Nat Barastad	Depth belo:	Not Reported	
Depth be 1:	Not Reported	Tape hold:	Not Reported	
Tape missi:	Not Reported	Tape cut:	Not Reported	
Water leve:	Not Reported	Water le 1:	Not Reported	
Cascading :	0	Pump type:	Not Reported	
Pump make:	Not Reported	Pump hp:	Not Reported	
Flowmeter :	Not Reported	Flowmeter1:	Not Reported	
Flowmete 1:	Not Reported	Flowmete 2:	Not Reported	
Accociated:	Not Papartad	Nhr of hour	Not Papartad	

Flowmete 2: Nbr of hou:

Work deepe:

Work alter:

Work exist:

Drill rota:

RIG GONE; TAG ATTACHED; STILL NO WELL LOG

Not Reported Not Reported

Not Reported

Not Reported

0

0

0

Associated: Deficiency:

Inspecti 3:

Work new:

Work conve:

Work aband:

Work other:

Not Reported

0

-1 0

Drill cabl:

0

Not Reported

NW

Drill ca 1: 0 Drill reve: 0 Drill re 1: 0 Drill auge: 0 0 Drill push: 0 Drill hand: 0 Drill holl: 0 Drill soni: 0 Drill othe: Not Reported Use domest: Use irriga: 0 Use commun: 0 Use indust: 0 Use livest: 0 0 0 Use dewate: Use monito: 0 0 Use therma: Use inject: Use piezom: 0 Use observ: 0 Use recove: 0 Use other: Not Reported Bentonite: 0 Conductivi: Not Reported Conducti 1: Not Reported Not Reported Measuremen: Well tag 1: Not Reported Bonded lic: Not Reported Unbonded I: Not Reported Bonded dri: Not Reported Unbonded d: Not Reported LANE County cod: Tax lot: Not Reported Township: 17 Township c: S Range: 2 W Range char: 22 Sctn: Qtr40: SE Qtr160: SW Latitude d: 44.07123 Longitude: 122.91843 Gps horizo: Not Reported Year const: 2004 Not Reported

BANDED Well tag a:

Date const:

Deficienci:

Inspected1:

Well tag 2: Not Reported Not Reported Depth:

Static wat: Not Reported Status of: CMP

Location r: Not Reported

Υ

KRB

Site visit: 0 Type of lo: Not Reported

Casing cap: SS Pictures t:

Street of: Not Reported

36485 CAMP CREEK RD, SPRINGFIELD Street of1:

Last updt: 07/12/2004 Last updt1: byrdkr

OWRD\migrate Rec creati: 06/01/2009 Rec crea 1:

44.07123 Newlat: Newlong: -122.91843 Site id:

ORI40000003992

OR WELLS ORI40000003991 **East** 1/2 - 1 Mile

Date con 1:

Previous i:

Wm region:

Higher

Drill ro 1:

0

Well inspe: 35751

Physical I: Inspection: 05/28/2004 Not Reported Startcard: Not Reported WI county: Not Reported WI nbr: Not Reported Startcard1: Not Reported

Well tag n: Not Reported No log:

Property o: Not Reported Inspecti 1: Not Reported Special st: Title: Not Reported Inspecti 2: Witnesses: Not Reported

Not Reported BRAINARD, WARREN Name owner:

Street: Not Reported City: Not Reported

0			
State:	Not Reported	Zip:	Not Reported
Phone home:	Not Reported	Phone comp:	Not Reported
Gps on wel:	0	Distance t:	Not Reported
Bearing to:	Not Reported	Drilling m:	Not Reported
Use of wel:	Not Reported	Drilling 1:	0
Rough log :	0	Inspected :	Not Reported
Well tag r:	Not Reported		
Monitoring:	Not Reported	Monitori 1:	0
Protective:	0	Well locke:	0
Consultant:	0	Water in v:	0
Seal test :	Not Reported	Samples ta:	0
Casing dia:	Not Reported	Csg above :	Not Reported
Csg gauge:	Not Reported	Borehole d:	Not Reported
Dedicated :	0	Access por:	0
Access p 1:	Not Reported	Measuring:	Not Reported
Measuring1:	0	Depth belo:	Not Reported
Depth be 1:	Not Reported	Tape hold:	Not Reported
Tape missi:	Not Reported	Tape cut:	Not Reported
Water leve:	Not Reported	Water le 1:	Not Reported
Cascading :	0	Pump type:	Not Reported
Pump make:	Not Reported	Pump hp:	Not Reported
Flowmeter :	Not Reported	Flowmeter1:	Not Reported
Flowmete 1:	Not Reported	Flowmete 2:	Not Reported
Associated:	Not Reported	Nbr of hou:	Not Reported
Deficiency:	Not Reported		
Inspecti 3:	RIG GONE; STILL NO TAG		
Work new:	0	Work deepe:	0
Work conve:	0	Work alter:	-1
Work aband:	0	Work exist:	0
Work other:	Not Reported	Drill rota:	0
Drill ro 1:	0	Drill cabl:	0
Drill ca 1:	0	Drill reve:	0
Drill re 1:	0	Drill auge:	0
Drill push:	0	Drill hand:	0
Drill holl:	0	Drill soni:	0
Drill othe:	Not Reported	Use domest:	0
Use irriga:	0	Use commun:	0
Use indust:	0	Use livest:	0
Use dewate:	0	Use monito:	0
Use therma:	0	Use inject:	0
Use piezom:	0	Use observ:	0
Use recove:	0	Use other:	Not Reported
Bentonite :	0	Conductivi:	Not Reported
Conducti 1:	Not Reported	Conductivi.	Not reported
Measuremen:	Not Reported		
Well tag 1:	Not Reported	Bonded lic:	Not Reported
Unbonded I:	Not Reported	Bonded dri:	Not Reported
Unbonded d:	Not Reported	County cod:	LANE
Tax lot:	Not Reported	County Cod.	LAINL
Township:	17		
Township c:	S		
Range:	2		
Range char:	W		
Sctn:	22		
Qtr40:	SE	Otr160:	SW
Qtr40: Latitude d:	44.07123	Qtr160:	SVV
	122.91843		
Longitude :			
Gps horizo:	Not Reported 2004		
Year const: Date const:		Date con 1:	Not Departed
Dale Collor.	Not Reported	Date COIL I.	Not Reported

Deficienci: Υ Previous i: Inspected1: **KRB** Wm region: NW

Well tag a: NONE YET

Not Reported Well tag 2: Not Reported Depth:

Static wat: Not Reported Status of: CMP

Location r: Not Reported

Site visit: Type of lo: Not Reported

Casing cap: SS Pictures t:

Not Reported Street of:

36485 CAMP CREEK RD, SPRINGFIELD Street of1:

Last updt: 05/28/2004 Last updt1: byrdkr

Rec creati: 06/01/2009 Rec crea 1: OWRD\migrate

Newlat: 44.07123 -122.91843 Newlong: ORI40000003991 Site id:

Higher

OR WELLS ORI40000003989 East 1/2 - 1 Mile

Well inspe: 35217 Physical I: 03/23/2004 Not Reported Inspection: Startcard: Not Reported WI county: Not Reported

WI nbr: Not Reported Startcard1: Not Reported

Well tag n: Not Reported No log: Not Reported Inspecti 1: Not Reported Property o: Special st: Title: Not Reported

Inspecti 2: Not Reported Witnesses: Not Reported

Name owner: BRAINARD, WARREN

Street: Not Reported City: Not Reported Not Reported Zip: Not Reported State: Not Reported Phone comp: Not Reported Phone home: Gps on wel: 0 Distance t: Not Reported Not Reported

Bearing to: Not Reported Drilling m:

Use of wel: Not Reported Drilling 1: 0

Inspected: Rough log: Not Reported

Well tag r: Not Reported Monitoring: Not Reported Monitori 1: 0

Protective: 0 Well locke: 0 0 0 Consultant: Water in v: Not Reported Seal test: Samples ta: 0

Casing dia: Not Reported Csg above: Not Reported Not Reported Borehole d: Not Reported Csg gauge:

Dedicated: Access por: Not Reported Measuring: Not Reported Access p 1:

Not Reported Measuring1: Depth belo: 0 Depth be 1: Not Reported Tape hold: Not Reported

Tape missi: Not Reported Tape cut: Not Reported Not Reported Water leve: Water le 1: Not Reported Cascading: 0 Pump type: Not Reported

Pump make: Not Reported Pump hp: Not Reported Not Reported Flowmeter: Flowmeter1: Not Reported Flowmete 1: Not Reported Flowmete 2: Not Reported Associated: Not Reported Nbr of hou: Not Reported

Deficiency: Not Reported

Inspecti 3: RIG SET UP ON HOLE

Work new: 0 Work deepe: 0 Work conve: 0 Work alter: -1 0 Work aband: 0 Work exist: 0

Work other: Not Reported Drill rota:

Drill cabl:

Drill reve:

Previous i:

Wm region:

Depth:

Status of:

Type of lo:

Pictures t:

Last updt1:

Rec crea 1:

0

0

NW

CMP

byrdkr OWRD\migrate

Not Reported

Not Reported

Drill re 1: 0 Drill auge: 0 0 Drill push: 0 Drill hand: 0 Drill holl: 0 Drill soni: Drill othe: Not Reported Use domest: 0 Use irriga: 0 Use commun: 0 Use indust: 0 Use livest: 0 0 0 Use dewate: Use monito: 0 0 Use therma: Use inject: Use piezom: 0 Use observ: 0 Use recove: 0 Use other: Not Reported Bentonite: 0 Conductivi: Not Reported Conducti 1: Not Reported Not Reported Measuremen: Well tag 1: Not Reported Bonded lic: Not Reported Unbonded I: Not Reported Bonded dri: Not Reported Not Reported LANE Unbonded d: County cod: Tax lot: Not Reported Township: 17 Township c: S Range: 2 W Range char: 22 Sctn: Qtr40: SE Qtr160: SW Latitude d: 44.07123 Longitude: 122.91843 Gps horizo: Not Reported Year const: 2004 Date const: Not Reported Date con 1: Not Reported

NONE YET Well tag a:

Well tag 2: Not Reported

U

KRB

0

0

Static wat: Not Reported

Location r: Not Reported

Site visit: 0 Casing cap:

Deficienci:

Inspected1:

Drill ro 1:

Drill ca 1:

Not Reported Street of: Not Reported

Street of1: 36485 CAMP CREEK RD, SPRINGFIELD

Last updt: 03/23/2004

Rec creati: 06/01/2009

44.07123 Newlat:

Newlong: -122.91843 Site id: ORI40000003989

> **OR WELLS** ORI40000003990

1/2 - 1 Mile Higher

East

Well inspe: 35334

Physical I: Inspection: 04/09/2004 Not Reported Startcard: Not Reported WI county: Not Reported WI nbr: Not Reported Startcard1: Not Reported

Well tag n: Not Reported No log:

Property o: Not Reported Inspecti 1: Not Reported Special st: Title: Not Reported Inspecti 2: Not Reported Witnesses: Not Reported

BRAINARD, WARREN Name owner:

Street: Not Reported City: Not Reported

State:	Not Paparted	7in:	Not Doportod
Phone home:	Not Reported Not Reported	Zip: Phone comp:	Not Reported Not Reported
Gps on wel:	0	Distance t:	•
•			Not Reported
Bearing to:	Not Reported	Drilling m:	Not Reported
Use of wel:	Not Reported	Drilling 1:	0 Nat Danastad
Rough log:	0 Not Bonostod	Inspected :	Not Reported
Well tag r:	Not Reported		
Monitoring:	Not Reported	Monitori 1:	0
Protective:	0	Well locke:	0
Consultant:	0	Water in v:	0
Seal test :	Not Reported	Samples ta:	0
Casing dia:	Not Reported	Csg above :	Not Reported
Csg gauge:	Not Reported	Borehole d:	Not Reported
Dedicated :	0	Access por:	0
Access p 1:	Not Reported	Measuring:	Not Reported
Measuring1:	0	Depth belo:	Not Reported
Depth be 1:	Not Reported	Tape hold:	Not Reported
Tape missi:	Not Reported	Tape cut:	Not Reported
Water leve:	Not Reported	Water le 1:	Not Reported
Cascading :	0	Pump type:	Not Reported
Pump make:	Not Reported	Pump hp:	Not Reported
Flowmeter :	Not Reported	Flowmeter1:	Not Reported
Flowmete 1:	Not Reported	Flowmete 2:	Not Reported
Associated:	Not Reported	Nbr of hou:	Not Reported
Deficiency:	Not Reported		
Inspecti 3:	RIG GONE		
Work new:	0	Work deepe:	0
Work conve:	0	Work alter:	-1
Work aband:	0	Work exist:	0
Work other:	Not Reported	Drill rota:	0
Drill ro 1:	0	Drill cabl:	0
Drill ca 1:	0	Drill reve:	0
Drill re 1:	0	Drill auge:	0
Drill push:	0	Drill hand:	0
Drill holl:	0	Drill soni:	0
Drill othe:	Not Reported	Use domest:	0
Use irriga:	0	Use commun:	0
Use indust:	0	Use livest:	0
Use dewate:	0	Use monito:	0
Use therma:	0	Use inject:	0
Use piezom:	0	Use observ:	0
Use recove:	0	Use other:	Not Reported
Bentonite :	0	Conductivi:	Not Reported
Conducti 1:	Not Reported		•
Measuremen:	Not Reported		
Well tag 1:	Not Reported	Bonded lic:	Not Reported
Unbonded I:	Not Reported	Bonded dri:	Not Reported
Unbonded d:	Not Reported	County cod:	LANE
Tax lot:	Not Reported	,	
Township:	17		
Township c:	S		
Range:	2		
Range char:	W		
Sctn:	22		
Qtr40:	SE	Qtr160:	SW
Latitude d:	44.07123		J
Longitude :	122.91843		
Gps horizo:	Not Reported		
Year const:	2004		
Date const:	Not Reported	Date con 1:	Not Reported
23.0 00.101.		20.0 00.1 1.	. tot rtoportou

Deficienci: Y Previous i: -1
Inspected1: KRB Wm region: NW

Well tag a: NONE YET

Well tag 2: Not Reported Depth: Not Reported

Static wat: Not Reported Status of : CMP

Location r: Not Reported

Site visit: 0 Type of lo: Not Reported

Casing cap: SS Pictures t: 0

Street of: Not Reported

Street of1: 36485 CAMP CREEK RD, SPRINGFIELD

Last updt: 04/09/2004 Last updt1: byrdkr

Rec creati: 06/01/2009 Rec crea 1: OWRD\migrate

 Newlat:
 44.07123

 Newlong:
 -122.91843

 Site id:
 ORI400000003990

AREA RADON INFORMATION

State Database: OR Radon

Radon Test Results

Zipcode	Num Tests	Maximum	Minimum	Average	# > 4 pCi/L
97478	3	1.3	0.3	0.7	0

Federal EPA Radon Zone for LANE County: 3

Note: Zone 1 indoor average level > 4 pCi/L.

: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.

: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for LANE COUNTY, OR

Number of sites tested: 19

 Area
 Average Activity
 % <4 pCi/L</th>
 % 4-20 pCi/L
 % >20 pCi/L

 Living Area
 0.850 pCi/L
 100%
 0%
 0%

 Basement
 1.360 pCi/L
 88%
 12%
 0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetlands Inventory Data Source: Oregon Geospatial Enterprise Office

Telephone: 503-378-2166

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)

Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Water Well Data

Source: Department of Water Resources

Telephone: 503-986-0843

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Locations

Source: Department of Geology and Mineral Industries

Telephone: 971-673-1540

A listing of oil and gas well locations in the state.

RADON

State Database: OR Radon Source: Oregon Health Services Telephone: 503-731-4272 Radon Levels in Orgeon

Area Radon Information

Source: USGS

Telephone: 703-356-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency

(USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones Source: EPA

Telephone: 703-356-4020

Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor

radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities

Source: Federal Aviation Administration, 800-457-6656


Epicenters: World earthquake epicenters, Richter 5 or greater

Source: Department of Commerce, National Oceanic and Atmospheric Administration

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.





Blue Water Ponds 52nd St & Highbanks Rd Springfield, OR 97478

Inquiry Number: 3791793.4

November 20, 2013

EDR Historical Topographic Map Report



EDR Historical Topographic Map Report

Environmental Data Resources, Inc.s (EDR) Historical Topographic Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topographic Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the early 1900s.

Thank you for your business.Please contact EDR at 1-800-352-0050 with any questions or comments.


Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Historical Topographic Map





TARGET QUAD

NAME: MARCOLA


MAP YEAR: 1950

PROVISIONAL SERIES: 15 SCALE: 1:62500 SITE NAME: Blue Water Ponds
ADDRESS: 52nd St & Highbanks Rd

Springfield, OR 97478 LAT/LONG: 44.0714 / -122.9372 CLIENT: US Army Corps of Engineers

CONTACT: Alison Burcham INQUIRY#: 3791793.4 RESEARCH DATE: 11/20/2013

Historical Topographic Map





TARGET QUAD

NAME: SPRINGFIELD

MAP YEAR: 1967

SERIES: 7.5 SCALE: 1:24000 SITE NAME: Blue Water Ponds

ADDRESS: 52nd St & Highbanks Rd


Springfield, OR 97478

LAT/LONG: 44.0714 / -122.9372

CLIENT: US Army Corps of Engineers

CONTACT: Alison Burcham INQUIRY#: 3791793.4 RESEARCH DATE: 11/20/2013

Historical Topographic Map





TARGET QUAD

NAME: SPRINGFIELD

MAP YEAR: 1986

PHOTOREVISED FROM: 1967

SERIES: 7.5 SCALE: 1:24000 SITE NAME: Blue Water Ponds

ADDRESS: 52nd St & Highbanks Rd

Springfield, OR 97478 LAT/LONG: 44.0714 / -122.9372 CLIENT: US Army Corps of Engineers

CONTACT: Alison Burcham INQUIRY#: 3791793.4 RESEARCH DATE: 11/20/2013